Technical Services Memo

Volume: 16 Number: 20 Date: October 13, 1994

Product Code: PA
Subject Code: AU
Part Number: 344A4189P11-14
LBI: 39060

CATEGORY: Audio Accessories

SUBJECT: MPA Speaker Mic fit to the radio**.**

Problem:

The plastic guide pin in the UDC connector body may not be perpendicular to the radio side rail mounting surface. This can cause interference and binding or damage to the indexing pin during attachment and removal of the connector. The angle of the guide pin is a function of the degree of tightness, or over torque, of the mounting screw located next to the guide pin, as the mounting screw gets over tightened the guide pin leans from perpendicular.

Solution:

To facilitate the connection of the speaker mic to the radio side connector loosen the case screw closest to the guide pin, 1/4 to 1/2 turn as required and use thumb pressure to manipulate the insert until the guide pin is perpendicular to the side connector body.