

Technical Services Memo

Volume: 30, Number: 01

January 24, 2008

Page 1 of 1

Product Code: HT, HM	System: EDACS, Conventional, P25
Part Number/Model: P7100, P5100	
Maintenance Document: TSM Volume# 26 Number 29B	

Category: Index

Subject: Technical Services Memo Index – 2007

Product Code	Issue	Subject	Date
KD	Vol 29,#1	E300P Maximum volume	01/10/07
HG HM HT	Vol 29,#2	M7100, P5100, P7100 Inverted LS Data	01/10/07
SX	Vol 29,#3	M-III TX Synthesizer lock-over current	01/15/07
91	Vol 29,#4	Install of R19a and later ProGrammer	01/25/07
D2 KE H9 HA HB HG HM			
HT MG PK PC PM	Vol 29,#5	Feature encryption programming	03/01/07
HB HG	Vol 29,#6	M7100/J725M Programmable RF output pwr	03/01/07
KD	Vol 29,#7	EDACS 300P Improved battery contacts	03/15/07
HA HB HG HM HT	Vol 29,#8	Unsupported Type 99 2-tone paging tones	04/27/07
HG HT	Vol 29,#9	Unintentional Disabling FIPS 140 radio	04/27/07
D2	Vol 29,#10	Prog. 7.5 kHz interstitial channels	04/27/07
H9	Vol 29,#11	LPE50/200 Low power with new PA module	05/11/07
HM HT	Vol 29,#12	External speaker microphone distortion	06/12/07
D2 HB HG	Vol 29,#13	Old SS-2000 siren cables on new radios	06/12/07
HG HM HT	Vol 29,#14	R13a flashcode and RPM radio programmer	06/12/07
H9 HA HM HT	Vol 29,#15	Accelerated swivel clip wear & poor fit	06/12/07
HT	Vol 29,#16	P7100 Immersion recertification	06/13/07
IMC MOM	Vol 29,#17	IMC/MOM Controller prom update for R8G	06/13/07
SX	Vol 29,#18	MASTR-III wide spaced VHF transmit freq	10/19/07
CH	Vol 29,#19	P5300/P5400 Tri-Chemistry charger	10/25/07
SX	Vol 29,#20	MASTR-III UHF RX Synthesizer fails lock	11/02/07
HM HT	Vol 29,#21	P5100/P7100 Very late low battery alert	11/29/07
HM HT	Vol 29,#21A	P5100/P7100 Very late low battery alert	11/29/07
HM HT	Vol 29,#21B	P5100/P7100 Very late low battery alert	11/30/07
CS SK	Vol 29,#22	OpenSky new BSC software compatibility	12/11/07

EDACS®

P25[™]

OpenSky®

NETWORKFIRST

Conventional