Technical Services Memo

Volume: 18 Number: 14 Date: 07/17/96

Product Code: PA
Subject Code: AU
Part Number: H29/53042013
LBI: 38606/31804

CATEGORY: PORTABLES

SUBJECT: REPLACEMENT MPA/MPD SPEAKER MIC CABLE

PROBLEM:

The origional replacement speaker mic cable is no longer available.

SOLUTION:

The 19B801586P1 speaker mic replaced the discontinued 19B801508P1 speaker mic. The H29/53042013 replacement cable/connector assembly is intended for the 19B801586P1 but must be used on the 19B801508P1. The following table outlines the wire color differences.

UDC PIN	508P1 CABLE	586P1 CABLE
E1	SHIELD	BLACK
E3	WHITE	WHITE
E4	RED	RED
E5	BROWN	BROWN
E6	----------	SHIELD
E12	BLUE	YELLOW
E13	----------	BLUE (NOT USED)