Technical Services Memo

Volume 15, Number 32
November 10, 1993
PC: PA
SC: PROGRAMMING
PN: TQ3339
LBI: N/A

CATEGORY: MPA
SUBJECT: MPA PROGRAMMING

All new production conventional MPA radios are now being built with the 19D903081G1 Controller Board.

When programming these radios, you have to identify them as "Digital" Radios in the TQ3339 programming menu. If not, you will be unable to program the radio and will get an "Error Check Connections" message.

W.L. Gallion
TAC Support