

Index of Technical Service Memos

Last change occurred on January 24, 2008

<u>Product Code</u>	<u>Issue</u>	<u>Subject</u>	<u>Date</u>
GN	Vol 30,#1	Technical Services Memo Index 2007	01/24/08
HM HT	Vol 30,#2	Improved knob cover retention	01/24/08
KD	Vol 29,#1	E300P Maximum volume	01/10/07
HG HM HT	Vol 29,#2	M7100, P5100, P7100 Inverted LS Data	01/10/07
SX	Vol 29,#3	M-III TX Synthesizer lock-over current	01/15/07
91	Vol 29,#4	Install of R19a and later ProGrammer	01/25/07
D2 KE H9 HA HB HG HM			
HT MG PK PC PM	Vol 29,#5	Feature encryption programming	03/01/07
HB HG	Vol 29,#6	M7100/J725M Programmable RF output pwr	03/01/07
KD	Vol 29,#7	EDACS 300P Improved battery contacts	03/15/07
HA HB HG HM HT	Vol 29,#8	Unsupported Type 99 2-tone paging tones	04/27/07
HG HT	Vol 29,#9	Unintentional Disabling FIPS 140 radio	04/27/07
D2	Vol 29,#10	Prog. 7.5 kHz interstitial channels	04/27/07
H9	Vol 29,#11	LPE50/200 Low power with new PA module	05/11/07
HM HT	Vol 29,#12	External speaker microphone distortion	06/12/07
D2 HB HG	Vol 29,#13	Old SS-2000 siren cables on new radios	06/12/07
HG HM HT	Vol 29,#14	R13a flashcode and RPM radio programmer	06/12/07
H9 HA HM HT	Vol 29,#15	Accelerated swivel clip wear & poor fit	06/12/07
HT	Vol 29,#16	P7100 Immersion recertification	06/13/07
IMC MOM	Vol 29,#17	IMC/MOM Controller prom update for R8G	06/13/07
SX	Vol 29,#18	MASTR-III wide spaced VHF transmit freq	10/19/07
CH	Vol 29,#19	P5300/P5400 Tri-Chemistry charger	10/25/07
SX	Vol 29,#20	MASTR-III UHF RX Synthesizer fails lock	11/02/07
HM HT	Vol 29,#21	P5100/P7100 Very late low battery alert	11/29/07
HM HT	Vol 29,#21A	P5100/P7100 Very late low battery alert	11/29/07
HM HT	Vol 29,#21B	P5100/P7100 Very late low battery alert	11/30/07
CS SK	Vol 29,#22	OpenSky new BSC software compatibility	12/11/07
HM HT	Vol 28,#1	P7100/P5100 Receive audio quality	01/05/06
HM HT	Vol 28,#2	P7100/P5100 I&Q and FM Modulation	01/05/06
TQ	Vol 28,#3	USB-to-Serial Adapter CN24741-0001	01/05/06
HG HT	Vol 28,#4	Multiple Key Manager Key Cards	01/12/06
CH	Vol 28,#5	Battery not charging - sleeve contacts	01/12/06
KE	Vol 28,#6	EDACS 500M stays in Transmit	01/27/06
HM HT	Vol 28,#7	P5100, P7100 CC Scan after power up	01/27/06
HG	Vol 28,#8	M7100 Erratic system selection	01/30/06
HG	Vol 28,#9	M7100 Unbalanced Dual Radio RX audio	03/13/06
HG	Vol 28,#9A	M7100 Unbalanced Dual Radio RX audio	05/17/06
HA HT MAHM	Vol 28,#10	Muffled transmit audio with nylon case	03/13/06
	Vol 28,#11	Battery Maintenance	03/23/06
91	Vol 28,#12	Radio personality programming limits	03/27/06
	Vol 28,#13	Battery date codes	04/04/06
	Vol 28,#13A	Battery date codes	12/19/06
	Vol 28,#13B	Battery date codes	12/10/07
HA HM HT	Vol 28,#14	J7000P/Pi, P5100 & 7100 PTT difficult	04/28/06
HA HM HT	Vol 28,#14A	J7000P/Pi, P5100 & 7100 PTT difficult	08/29/07
HA HM HT	Vol 28,#15	NiMH capable portable battery chargers	04/28/06
HA HB HG HM HT	Vol 28,#16	Emergency declaration disables SCAN	04/28/06
HHC	Vol 28,#17	HHC microphone audio freq flatness	06/27/06
HM HT	Vol 28,#18	Radio PTT could be falsely activated	08/28/06
GETC	Vol 28,#19	DownLink RS232 connect direct to IMC	09/20/06
SD	Vol 28,#20	Prism Mastr BST modulator reliability	10/03/06

M-803 VR-803	Vol 28,#21	Loose GPS connector on M-803 & V-TAC	10/03/06
CH	Vol 28,#22	Battery charging in E300P charger	10/03/06
D2 HB HG	Vol 28,#23	Interfacing to external audio devices	10/03/06
CISCO	Vol 28,#24	Cisco AC power cord safety defect	10/06/06
SR	Vol 28,#25	Aux Receiver battery alarm w/new PS	10/26/06
HG HB	Vol 28,#26	M7100 Fixed audio output level	11/08/06
Harris	Vol 28,#27	Harris Intraplex MA-417& MA-417A RS232	11/09/06
91	Vol 28,#28	Reading Flash & DSP code from radio	11/09/06
D2 HA PK	Vol 27,#1	Over-the-air erasure DES/VGE/AES Keys	01/03/05
A7 V-TAC	Vol 27,#2	Verify GPS operation in M-803 & V-TAC	01/07/05
D2 H9 HA HB HG	Vol 27,#3	Phantom Emergency Display	01/28/05
D2 H9 HA HB HG	Vol 27,#3A	Phantom Emergency Display	02/15/05
H9 HA KB PK	Vol 27,#4	Speaker mic jack defect - no RX audio	01/28/05
MS GPS	Vol 27,#5	Conexant modem shelf modification	02/01/05
D2 HB HG	Vol 27,#6	Orion J725 M7100 Power cable screw	02/01/05
HA HM HT	Vol 27,#7	Jaguar J700P P7100 P5100 programming	03/03/05
HA HM HT	Vol 27,#8	J700P P7100 P5100 program/flash mode	03/03/05
HA HB HG HM HT	Vol 27,#9	Direct connect programming cables	03/05/05
HA HB HG HM HT	Vol 27,#10	Re-Use of Factory Default personality	03/08/05
HG	Vol 27,#11	M7100 off frequency	03/11/05
HG	Vol 27,#11A	M7100 off frequency	04/29/05
GP	Vol 27,#12	Panther portable programming	03/16/05
HA HB HG HT	Vol 27,#13	Keyloader option for Mobile & Portable	04/06/05
D2 HB HG	Vol 27,#14	Mobile over voltage protection	04/07/05
HB HG	Vol 27,#15	M7100 & J725 Speaker Pop	05/06/05
HM HT	Vol 27,#16	P7100/P5100 Volume & Channel ring nuts	05/06/05
HM HT	Vol 27,#16A	P7100/P5100 Volume & Channel ring nuts	05/25/06
HM HT	Vol 27,#16B	P7100/P5100 Volume & Channel ring nuts	04/04/07
TQ	Vol 27,#17	ProGammer - What version used	05/06/05
	Vol 27,#18	Battery Date Codes	06/08/05
HA HB HG HM HT	Vol 27,#19	No Wide Area Scan	06/16/05
HA HB HG HM KE	Vol 27,#20	No Status/Message after ProScan to sys	06/16/05
HM HT	Vol 27,#21	P7100/P5100 Channel knob comes off	06/29/05
HM HT	Vol 27,#21A	P7100/P5100 Channel knob comes off	04/04/07
HT	Vol 27,#22	P7100 Immersion recertification	07/29/05
KD	Vol 27,#23	E300P improved mechanical components	07/29/05
HG	Vol 27,#24	M7100 Dual Control audio/relay switch	08/01/05
VJ	Vol 27,#25	VJ Voter "late enter" software update	08/05/05
PC	Vol 27,#26	PCS Re-Flash Programming Procedure	11/02/05
D2 HB HG	Vol 27,#27	Open mic during Emergency Auto-Key	11/03/05
TQ	Vol 27,#28	ProGammer R18B legacy support	11/18/05
HG HM HT	Vol 27,#29	M7100 P7100 5/1 Tone encoding	12/23/05
GN SV	Vol 26,#1	2003 Technical Service Memo Index	01/06/04
H9	Vol 26,#2	LPE-200 Early battery alert	01/06/04
PC	Vol 26,#3	EDACS PCS 800 MHz RF amp modules	02/05/04
KA KB	Vol 26,#4	Panther 300M TCXO adjustment	02/05/04
HHC	Vol 26,#5	Hand Held Controller display shut down	03/16/04
D2	Vol 26,#6	Orion audio hiss in dual-radio install	03/16/04
KD	Vol 26,#7	EDACS 300P power-up & cold temperature	03/17/04
SX	Vol 26,#8	MASTR-III TX Low Pass Filter noise	03/17/04
GETC	Vol 26,#9	GETC confirmation time - late entry	03/17/04
HA	Vol 26,#10	Jaguar 700P Battery Alert & Meter	03/24/04
C3	Vol 26,#11	C3 Maestro RS-422 configuration	03/26/04
GETC	Vol 26,#12	Downlink Turbo software mismatch	04/02/04
SX	Vol 26,#13	MASTR-III Hum & Noise in 12.5 kHz	04/14/04
HA HB HT	Vol 26,#14	Jaguar700P/Pi/725M,P7100 ProScan wrong	04/26/04
H9 PA PK	Vol 26,#15	Battery capacity specs. for analyzer	04/27/04
H9	Vol 26,#16	LPE battery alert and PTT lockout	04/27/04
CSD	Vol 26,#17	CSD - Security - SA password MANDATORY	04/29/04

CSD	Vol 26,#18	CSD - Virus SQLSpida.a.Worm URGENT	04/29/04
SC	Vol 26,#19	IEA Wiring may short to rack ground	05/18/04
CSD	Vol 26,#20	CSD Processes/Services will not start	05/20/04
CSD	Vol 26,#21	CSD Blue Screen - non-existent port	05/20/04
IMC	Vol 26,#22	IMC Logout polling configuration	06/09/04
KB	Vol 26,#23	Panther 300P six to 16 chan. upgrade	06/09/04
HA HT	Vol 26,#24	P7100 G-Star ANI / Emergency	06/11/04
HA HT	Vol 26,#25	P7100 Intermittent garbled ProVoice	06/11/04
KE KM	Vol 26,#26	E500M & KMC LCD Display failures	06/15/04
GP	Vol 26,#27	Panther antenna - Cut or not to cut	06/17/04
D2	Vol 26,#28	Orion and error 0612	06/25/04
HA	Vol 26,#29	J700P/P7100 replacement control knobs	06/25/04
HA	Vol 26,#29A	J700P/P7100 replacement control knobs	10/14/04
HA	Vol 26,#29B	J700P/P7100 replacement control knobs	04/04/07
PK	Vol 26,#30	M-RK radio will not turn-off	06/25/04
KD	Vol 26,#31	EDACS 300P EMERGENCY	08/02/04
HT	Vol 26,#32	P7100 VHF/UHF P25 False mute or unmute	08/02/04
GN SV	Vol 26,#33	Site Grounding Standards revised	08/19/04
HA HT	Vol 26,#34	P7100/J7100P CC SCAN on power up	08/23/04
SX	Vol 26,#35	MASTR-III TX synthesizer fails to lock	08/26/04
CH	Vol 26,#36	Universal Rapid Charger won't start	09/20/04
D2 HT HA	Vol 26,#37	Orion, M7100 & Jaguar 725M self PTT	10/05/04
D2 HT HA	Vol 26,#37A	Orion, M7100 & Jaguar 725M self PTT	01/05/05
HA	Vol 26,#38	Jaguar 725M intermittent CCSCAN	10/06/04
HM HT	Vol 26,#39	P7100/P5100 "Tinny" & distorted audio	10/06/04
HA HT	Vol 26,#40	P7100 Disable display & LED feature	10/06/04
IEA	Vol 26,#41	IEA Connection - Serial to IP LAN	10/08/04
EDG	Vol 26,#42	EDG Modem CTS LED's continuously lit	10/15/04
SX	Vol 26,#43	MASTR-III 4-Wire audio looped RX to TX	10/18/04
D2 HG	Vol 26,#44	ORION/M7100 Control - PTT & Hookswitch	11/04/04
CSD	Vol 26,#45	CSD activity detail loss - SQL changes	11/05/04
D2 PK	Vol 26,#46	MRK & ORION narrowband configuration	11/12/04
HG	Vol 26,#47	M7100 Improved ProVoice transmit audio	12/03/04
91 GN SV	Vol 26,#48	ProGammer Windows 2000/XP read/write	12/06/04
91 GN SV	Vol 26,#48A	ProGammer Windows 2000/XP read/write	01/03/06
D2	Vol 26,#49	Orion ERR=0603	12/06/04
HA	Vol 26,#50	Jaguar rear casting slot rail failure	12/06/04
HA HT	Vol 26,#51	All portables - "D" ring wear	12/06/04
SX	Vol 26,#52	MASTR-III synth. need new software	12/13/04
HB	Vol 26,#53	Jaguar J725M has no P25 Modulation	12/15/04
GN SV	Vol 25,#1	2002 Technical Service Memo Index	01/09/03
D2 HB	Vol 25,#2	Siren/Light programming in Dual-Radios	01/15/03
B3E SX	Vol 25,#3	MASTR-IIe Test Meter - needle pegs	01/24/03
91 SW	Vol 25,#4	ProGammer and Windows 2000/XP	01/20/03
KB	Vol 25,#5	Panther 300P PTT button improved	02/19/03
H9	Vol 25,#6	LPE 800&900 - TCXO replacement SPK0206	03/18/03
KD	Vol 25,#7	EDACS 300P internal microphone	03/26/03
KD	Vol 25,#8	EDACS 300P Volume knob improved	03/27/03
KD	Vol 25,#8A	EDACS 300P Volume knob improved	08/02/04
CH	Vol 25,#9	Charger sleeve increases charge time	04/02/03
CD SA	Vol 25,#10	CSD and SIM downlink configuration	04/04/03
D2 H9 PK	Vol 25,#11	Orion-MRK-LPE-Prism CTS/RTS lead issue	04/10/03
HA	Vol 25,#12	Jaguar700P GRP/VOLUME control retainer	04/10/03
HA	Vol 25,#12A	Jaguar700P GRP/VOLUME control retainer	12/15/03
D2 HB	Vol 25,#13B	Jaguar725 & Orion compatible access.	09/12/03
H2	Vol 25,#14A	M-RK Charger w/Orion Control - display	04/15/03
KA	Vol 25,#15	Panther 300M upgrade 6 to 16 channels	04/17/03
D2	Vol 25,#16	Orion VHF Synthesizer error code 0401	04/17/03
GP GT	Vol 25,#17	Cougar/Panther400P error on empty chan	04/22/03
HA H9 PK	Vol 25,#18	Portable antenna & bypass connector	04/22/03

GP GT	Vol 25,#19	Panther/Cougar Charger Firmware V 3.09	04/22/03
KM	Vol 25,#20	KMC R2A Flashcode & ProGammer issues	04/23/03
GP GT	Vol 25,#21	Panther/Cougar Poor battery performance	06/05/03
H9	Vol 25,#22	LPE new C-56 DSP board won't plug	06/05/03
GP GT	Vol 25,#23	Panther405/605 incompatible UDC access	06/05/03
HA	Vol 25,#24	J700P C5416 ProFile Mangr & ProGmr R10a	06/05/03
GETC	Vol 25,#25	GETC programming interrupts operation	06/27/03
SIM	Vol 25,#26	Recommended SIM personality programming	07/09/03
D2 HB HG	Vol 25,#27	Orion Control unit - knobs loosen	07/30/03
H9 KP	Vol 25,#28	Portable battery contacts changed	07/30/03
D2 PK HA HB HT	Vol 25,#29	Feature Encryption Programming Update	08/20/03
KE	Vol 25,#30	EDACS 500M Programming Mode	08/20/03
KE	Vol 25,#30A	EDACS 500M Programming Mode	10/09/03
H9	Vol 25,#31	LPE Rear casting improved	09/15/03
HA	Vol 25,#32	Jaguar700P Battery alert	09/23/03
SC	Vol 25,#33	CPTC Programming with WinGETC	10/01/03
SX	Vol 25,#34	800 MHz PA U2 hybrid substitution	10/07/03
SC	Vol 25,#35	Vertical Turbo Card programming	10/07/03
KD	Vol 25,#36	EDACS 300P high deviation of LSD	10/10/03
KD	Vol 25,#36A	EDACS 300P high deviation of LSD	12/29/03
KD	Vol 25,#36B	EDACS 300P high deviation of LSD	03/24/04
KD	Vol 25,#37	EDACS 300P self PTTs	10/10/03
CH	Vol 25,#38	Universal charger status indicators	10/10/03
PK	Vol 25,#39	M-RK TCXO substitution to SPK0307	11/05/03
KH	Vol 25,#40	Panther 500P squelch adjustments	11/05/03
CD	Vol 25,#41	CSD Backup tape eject notification	11/26/03
GP	Vol 25,#42	Panther Vehicle Charger & NiMH battery	12/15/03
HA H9	Vol 25,#43	Jaguar 700P Intermittent volume	11/26/03
H9	Vol 25,#44	LPE "Radio Type" Invalid	12/09/03
IMC	Vol 25,#45	IMC AIC Audio board identification	12/15/03
D2 HB	Vol 25,#46	ORION/J725 Control Head Key Caps illum	12/15/03
H9	Vol 25,#47	LPE-200 Receive audio popping	12/16/03
H9	Vol 25,#47A	LPE-200 Receive audio popping	02/06/04
PK	Vol 25,#48	M-RK RF PA replacement modules	12/16/03
PA	Vol 25,#49	MPA Matching battery baseplate/covers	12/16/03
A7	Vol 25,#50	V-TAC - Prevent "Rolling" operation	12/23/03
A7	Vol 25,#50A	V-TAC - Prevent "Rolling" operation	02/23/04
A7	Vol 25,#50B	V-TAC - Prevent "Rolling" operation	04/12/04
GN SV	Vol 24,#1	2001 Technical Service Memo Index	01/22/02
CH PC PK	Vol 24,#2	PCS & MR-K Charger flashes RED	01/28/02
B3E SX	Vol 24,#3	MASTR-III Falsing Tone Functions	01/28/02
KD	Vol 24,#4A	EDACS 300P Late Entry/Retry	02/01/02
D2	Vol 24,#5A	SS2000GE siren module turns self ON	04/03/02
SX	Vol 24,#6	MASTR-III UHF PA, Q7 runs hot	04/18/02
H9	Vol 24,#7	Jaguar Belt-Loop D-ring doesn't fit	04/18/02
CH	Vol 24,#8	Batteries stop charging early	04/19/02
GETC SX	Vol 24,#9	GETC False emergencies on GID 32	05/02/02
GM	Vol 24,#10	Panther 200/400M Bad RX sensitivity	06/13/02
C3	Vol 24,#11	C3 Maestro and KNOX-BOX@ paging	09/10/02
HA	Vol 24,#12	Jaguar KR D 103 161/1 & /2 random RESET	09/10/02
H9	Vol 24,#13A	LPE-50 & 200 changing RF power levels	10/16/02
CH	Vol 24,#14	J700p and Universal Rapid Charger	09/30/02
GP	Vol 24,#15	Panther 400p 600p 625p Firmware upgrade	09/30/02
CD	Vol 24,#16	CSD Defaults - Don't Use	10/03/02
GP	Vol 24,#17	Panther TOPB200 Battery Cell Rattle	10/08/02
SD	Vol 24,#18	PRISM MASTR BSC parameters lost	10/08/02
H9	Vol 24,#19	LPE Leather carry cases	12/31/02
GP	Vol 24,#20	Panther 625 HOME BUTTON programming	11/07/02
IMC	Vol 24,#21	IMC HDLC Failures with software update	11/08/02
HA	Vol 24,#22	Jaguar speaker/mic UDC 1/4 turn screw	11/15/02

D2 HB	Vol 24,#23	Orion & Jaguar Control Head seals	11/15/02
D2 HB	Vol 24,#24	Orion dual radio - RX buzzing	12/31/02
KD CH	Vol 24,#25	EDACS 300p Charger micro failure	12/31/02
GN SV	Vol 23,#1	2000 Technical Service Memo Index	03/29/01
C3	Vol 23,#2	Maestro POWER ON indicator for EAE	04/04/01
D2 PK	Vol 23,#3	Late entering on 380-403 MHz EDACS	04/24/01
GETC SX	Vol 23,#4	M-III GETC Interconnect Harness	08/09/01
GB	Vol 23,#5	MPT Cougar CTCSS encode deviation	09/30/01
SM	Vol 23,#6	SIM Display Reversed when Reset	09/30/01
SR	Vol 23,#7	Aux RX Line Driver Protection	09/30/01
CD	Vol 23,#8	CSD - Adding USERS & GROUPS	09/30/01
SM	Vol 23,#9	VAX SM Aborted Activity Processes	09/30/01
D2	Vol 23,#10	Orion Control Head Burned Trace	10/04/01
D2	Vol 23,#11	Orion "New" Control Unit - L702 damage	10/04/01
KD	Vol 23,#12	EDACS 300P Cracked front covers	10/05/01
D2	Vol 23,#13	Orion Control Head ID ERR=0612	10/04/01
GB	Vol 23,#14	Cougar MPT - Single PTT operation	10/08/01
JA	Vol 23,#15	Jaguar 700 Speaker Mic distortion	12/21/01
PK	Vol 23,#16	MR-K Antenna switch contacts	12/21/01
PK	Vol 23,#17	MR-K Control/Logic & RF compatibility	12/21/01
PK	Vol 23,#18	MR-K Escutcheon detaches from housing	12/21/01
D8 PM	Vol 23,#19	Desk-Top power supply 19A704647	12/21/01
CD	Vol 23,#20	CSD Handling of System Assigned IDs	12/26/01
C3	Vol 23,#21	C3 Maestro Ringing won't stop on IND	12/26/01
SX	Vol 23,#22	MASTR-III Station service speaker hum	12/26/01
HA	Vol 23,#23A	Jaguar batteries fail to charge	01/09/03
GN SV	Vol 22,#1	1999 Technical Service Memo Index	01/14/00
SX	Vol 22,#2	800 PA Power Drift	01/14/00
SX	Vol 22,#3	800 PA - New Alignment Improves Reliability	01/31/00
SX	Vol 22,#3A	800 PA - New Alignment Improves Reliability	09/14/00
GETC	Vol 22,#4	WinGETC patches for FAIL SOFT & DIGITAL VOICE	06/16/00
TQ	Vol 22,#5A	Radio Programmer causes NO KEY error	06/12/01
GN SV	Vol 21,#1	1998 Technical Service Memo Index	03/08/99
SX	Vol 21,#2A	UHF PA - Special Solder SPK-9812 & SPK-9813	04/21/99
GETC	Vol 21,#3	Dead Turbo	03/09/99
GETC	Vol 21,#4	Turbo Serial Number Repair	03/09/99
SD	Vol 21,#5	TCP/IP General Information	03/09/99
MG MH ML	Vol 21,#6	MLS-II & Monogram Conventional - Y2K	04/27/99
	Vol 21,#7	Orion & MDX (TSM withdrawn)	
B3 D2 SX	Vol 21,#8	Low Power Output - Poor Connections	08/11/99
SM	Vol 21,#9	Y2K Issues using R7F Software (v 6.42)	08/31/99
D2	Vol 21,#10	Orion Synthesizer/Exciter board replacement	10/20/99
NP	Vol 21,#11	NPC-50 Disassembly Instructions	10/20/99
MG	Vol 21,#12	Monogram Mobile - Display Illumination	10/20/99
MG	Vol 21,#13	Monogram Mobile - Power Up Channel	10/20/99
PC PD PK PL	Vol 21,#14	Portable Radio - Battery Date Codes	10/20/99
GN SV	Vol 20,#1	1997 Technical Service Memo Index	06/01/98
JP	Vol 20,#2	IPE EDACS Access at High Power	06/02/98
KP	Vol 20,#3	KPC DTMF Distortion	06/03/98
KP	Vol 20,#4	KPC Speaker Mic - High Sensitivity	06/04/98
GETC SX	Vol 20,#5	Downlink Failure with R8A Station	06/05/98
Various	Vol 20,#6A	Battery Date Codes	10/20/99

SX	Vol 20,#7	M-III PA & Fan Control Failure	09/25/98
SX	Vol 20,#8	Damage to PA Power Control	09/26/98
SX	Vol 20,#9	M-III 800 TX Synth - Caps Fail & RF	09/27/98
MG	Vol 20,#10	Improvements to the Monogram Portable & Mobile reference oscillator circuits	09/28/98
C3	Vol 20,#11	C3 Maestro NT & DOS Console patching incompatibility	11/11/98
GN SV	Vol 19,#1	1996 Technical Service Mem Index	01/01/97
GN	Vol 19,#2A	Repair & Return of Critical Equipment	01/27/97
KP	Vol 19,#3A	PC Programmer release v. 3.0 for KPC	04/14/97
SX	Vol 19,#4	Damage to PA RF Transistors	04/14/97
GETC	Vol 19,#5	GETC Mod Instructions for M-III	04/14/97
KP	Vol 19,#6	KPC Acoustic Microphone Sensitivity	04/14/97
B3e SX	Vol 19,#7	MASTR-III & IIE Battery Charger	07/29/97
PC	Vol 19,#8	PCs Logic Board Kills Display	07/30/97
KP PC H9	Vol 19,#9	Modifications to the Universal Charger	04/14/97
KP	Vol 19,#10	KPC Programmer V4.0 won't write-COMM2	08/13/97
GN SV	Vol 18,#1	1995 Technical Service Memo Index	02/13/96
B3 GETC S3	Vol 18,#2	GETC slows TX audio attack time	02/13/96
GN SV	Vol 18,#3C	TAC Support Product listing updated	11/21/96
PC	Vol 18,#4	PCs sleeve charger contact mod	05/21/96
PA	Vol 18,#5	MPA LCD display 19C337096G1 part sub	05/21/96
MG	Vol 18,#6	Monogram (mobile) mic sensitivity	05/21/96
PC	Vol 18,#7	PCs BNC antenna connector changed	05/21/96
PC	Vol 18,#8	PCs battery improvements, short case	05/21/96
PA	Vol 18,#9	MPA with wet UDC may lock up logic	05/21/96
PA	Vol 18,#10	MPA battery switch failures	05/21/96
N9	Vol 18,#11	Ranger 800 EDACS modulation; LBI error	07/17/96
PA PD PK TQ	Vol 18,#12	TQ0609 for MPA, MPD, MRK revised	07/17/96
PA	Vol 18,#13	MPA 900 MHz Reference Oscillator	07/17/96
PA	Vol 18,#14	MPA/MPD Speaker Mic Cable Replacement	07/17/96
SX	Vol 18,#15	M-III VHF PA overheating - mica caps	11/12/96
67 B3 S3	Vol 18,#16	M-II UHF PA transistor sub to MRF646	11/12/96
SX	Vol 18,#17	M-III UHF RX tuning - RX SYNTH FL1	11/12/96
B3 S3 GETC	Vol 18,#18	VG late entry - GETC prom 19A149219G9	11/12/96
GN SV	Vol 17,#1	1994 Technical Service Memo Index	01/23/95
PM	Vol 17,#2	MDX Internal/External speaker options	01/23/95
D2	Vol 17,#3A	Orion Siren/Light wiring, installation	02/02/95
D2	Vol 17,#4	Orion Programming and Keyload cables	01/23/95
PM	Vol 17,#5B	Feature Encryption Programming	10/20/00
D2 PK	Vol 17,#6	EDACS-3 / Conv-1 Ver 7.0 PC programmer	01/23/95
D2	Vol 17,#7	Orion & MRK HOME key programming	01/23/95
D2	Vol 17,#8	Orion dual control requirements	01/23/95
D2	Vol 17,#9	Orion keypad programming	01/23/95
D2	Vol 17,#10A	Orion / MRK Prog. replacement logic bd	02/02/95
D2	Vol 17,#11	Orion & MRK Flash & ADI code	01/23/95
PA	Vol 17,#12	MPA conventional GE*STAR Emergency	01/23/95
PC	Vol 17,#13	PCs Erratic scan, audio chopping	02/02/95
B3E	Vol 17,#14	MASTR-IIe DCG modulation waveform	04/07/95
FM	Vol 17,#15	FMD ignition sense fuse	04/07/95
MG	Vol 17,#16	MONOGRAM PC programming TQ3375 ver. 3	04/07/95
MG	Vol 17,#17	MONOGRAM Synthesizer "out of lock"	07/14/95
GN SV	Vol 16,#1	1993 Technical Service Memo Index	03/10/94
MG	Vol 16,#2	MONOGRAM UHF mobile TX noise	03/10/94
17 SC B3E SX	Vol 16,#3	800 MHz 24V Pwr supply fuse failure	03/10/94
B3 SX S3	Vol 16,#4	800 MHz 24V RF PA - change C2	03/10/94
PC	Vol 16,#5	PCs UHF spkr mic - RFI causes RESET	05/05/94

MG	Vol 16,#6	MONOGRAM mobile mic - sticking PTT	05/06/94
PC	Vol 16,#7	PCs EDACS retry access - G11 flashcode	05/06/94
MG	Vol 16,#8	MONOGRAM UHF mobile-hum,noise,CG dist.	06/23/94
SX	Vol 16,#9	MASTR-III and GETC data errors	09/13/94
PA	Vol 16,#10	MPA Battery flag, TX hum & noise	09/13/94
SX	Vol 16,#11	MASTR-III 800 TX synthesizer unlock	09/13/94
SX	Vol 16,#12	MASTR-III Digital CG modulation	09/13/94
B3	Vol 16,#13	MASTR-II 900 MHz TX spurious	09/13/94
SX	Vol 16,#14	MASTR-III RF test fixture TQ0650	09/13/94
PC	Vol 16,#15	PCs UHF RFI Kit SPK9301	10/13/94
D2 PK	Vol 16,#16	ORION & M-RK Group 13 & 14 Flashcode	10/13/94
D2	Vol 16,#17	ORION Microphone hanger 344A4678P1	10/13/94
CH PK	Vol 16,#18	M-RK Vehicle Charger with dead battery	10/13/94
CH PK	Vol 16,#19	M-RK rev "A" Vehicle Charger SW5 wrong	10/13/94
PA	Vol 16,#20	M-PA UDC connector binding guide pin	10/13/94
TM	Vol 16,#21	TMX8712 replacement handset SPK9401/04	10/21/94
GN SV	Vol 15,#1	1992 Technical Service Memo Index	01/25/93
TL	Vol 15,#2	TL-800 Controls inoperative, Asleep	01/25/93
TL	Vol 15,#3	MDS Digital CG voice blocking	01/25/93
S8	Vol 15,#4	S825 power-up in "OFF" condition	01/25/93
PK	Vol 15,#5	M-RK Programming cable TQ3368	03/03/93
MG	Vol 15,#6	Monogram beeps when changing channels	03/03/93
CN NP TM	Vol 15,#7	Logic BD 19D901690G11 C708 reversed	03/03/93
PA	Vol 15,#8	M-PA Programming cable TQ3311 - FLASH	03/03/93
TM	Vol 15,#9	TMX Logic board 19D901690G11 software	04/07/93
PM	Vol 15,#10	MDR/MDX receive audio hiss and noise	04/07/93
PC	Vol 15,#11	PCs (D/F) loses memory in charger	04/07/93
TL	Vol 15,#12	MDS Conventional synth. instability	05/18/93
PC	Vol 15,#13	PCs PLUS programming with Ver. 3.0	05/18/93
AD SV	Vol 15,#14	Changed format & to Tech Assist. Cntr	07/15/93
PA	Vol 15,#15	MPA UDC receive audio level	07/15/93
PA	Vol 15,#16	MPA Receiver microphonics	07/15/93
PA	Vol 15,#16A	MPA Receiver microphonics - P/N fixed	09/09/93
PA	Vol 15,#17	MPA Volume pot mounting instructions	07/15/93
PM	Vol 15,#18	MDR/MDX Busy Tone filter heat effects	07/15/93
S6 QC05	Vol 15,#19	S550 & VG9600 programming	07/15/93
MT	Vol 15,#20	MTD will not program with TQ3370 box	07/15/93
B3 S3	Vol 15,#21	MASTR-II & IIe UHF FM exciter spurs	07/15/93
B3 SX	Vol 15,#22	MASTR-IIe & III programming, F7 RESET	07/15/93
N3 N9 QC05	Vol 15,#23	TQ3334 V-4 DELTA/RANGR install missing	09/09/93
PA	Vol 15,#24	M-PA Flashcode interface TQ3370	09/09/93
S8	Vol 15,#25	S825 Control latches vehicle horn on	09/09/93
N9	Vol 15,#26A	EDACS RANGR 800 miss call @ high temp	09/09/93
PC	Vol 15,#27	PCs speaker microphone & RFI	11/10/93
PC	Vol 15,#27A	PCs speaker microphone & RFI	03/10/94
PC	Vol 15,#28	PCs UHF RFI kit SPK9301 - UDC & VCO	11/10/93
PC	Vol 15,#28A	PCs UHF RFI kit SPK9301 updated	04/21/94
N9	Vol 15,#29	RANGR modification to 32 channels	11/10/93
MG	Vol 15,#30	MONOGRAM mobile TX audio gain	11/10/93
MG	Vol 15,#30A	Discard/withdraw TSM V15#30	03/10/94
AD	Vol 15,#31	Technical Service Memo Errata	11/10/93
PA	Vol 15,#32	M-PA Programming - Identify as DIGITAL	11/10/93
GN SV	Vol 14,#1	1991 Technical Service Memo Index	02/12/92
ML	Vol 14,#2	MLS-II Digital CG inverted	02/12/92
PC	Vol 14,#3	PCs Digital CG inverted	02/12/92
MP	Vol 14,#4	MPI-II Synthesizer board - pins long	02/12/92
CN NP TM	Vol 14,#5	TMX & MCS Logic board EPROM change	03/20/92
MP	Vol 14,#6	MPI-II standby current drain	03/20/92
67 B3 S3	Vol 14,#7	MASTR-II VHF PA driver 19D424309 Rev J	03/20/92

P9		Vol 14,#8	MPS Loose baseplate drive pins	03/20/92
PA		Vol 14,#9	M-PA Loss of receive audio at T2	03/20/92
67 B3 S3 SX		Vol 14,#10	MASTR-IIe & III power supply hum	05/28/92
B3		Vol 14,#11	MASTR-IIe antenna relay switch time	05/28/92
CH		Vol 14,#12	Universal rapid charger flashing red	05/28/92
MP		Vol 14,#13	MPI-II UHF PA failures	07/08/92
N3		Vol 14,#14	DELTA UHF TX spurs - revision change	07/14/92
S3 B3 67		Vol 14,#15	GETC cable harness improved SPK-9027	07/14/92
S8		Vol 14,#16	S825 EE potentiometer falsing	07/14/92
SV		Vol 14,#17	TNC and "N" connectors not compatible	07/14/92
N3 N9		Vol 14,#18	DELTA microprocessors and applications	07/14/92
NP		Vol 14,#19	MVS EE-PROM memory loss	09/16/92
N3		Vol 14,#20	DELTA 40W VHF TX spurious oscillations	09/16/92
GN SV		VOL 13,#1	1990 TECH SVS. MEMO INDEX	01/02/91
FM		VOL 13,#2	FMD 9 VOLT REGULATOR FAILURES - REV E	01/09/91
ML		VOL 13,#3	MLS-II TRANSIENT VOLTAGE PROTECTION	01/31/91
PD PV		VOL 13,#4	MPD 800 MHz MICROPHONICS	01/31/91
PA		VOL 13,#5	MPA / MTL - FAILURE OF Q-10	02/05/91
PA		VOL 13,#5A	MPA / MTL - FAILURE OF Q-10 (REVISED)	04/24/91
17 B3 S1 S3		VOL 13,#6	M-II GE-MARC STATION ACQUISITION TIMING	03/05/91
QC05		VOL 13,#7	VOICE GUARD W/ DUAL CONTROL - TX AUDIO	03/01/91
S7		VOL 13,#8	S700 W/DUAL CONT.-PTT TAKEOVER LOCKS UP	03/01/91
S8		VOL 13,#9	S825 W/DUAL CONTROL - SOFTWARE	03/05/91
TM		VOL 13,#10	TMX 84/86 DROPPING CALLS - SYNTH. LOCK	03/05/91
17 B3 S1 S3		VOL 13,#11	GE-MARC STATION SQUELCH CLIP OF BUSY TN	03/05/91
17 B3 S1 S3		VOL 13,#11A	GE-MARC STATION SQUELCH CLIP OF BUSY TN	06/04/91
P5		VOL 13,#12	MPI CHARGER MODIFICATIONS FOR 600 MAH	03/06/91
P5		VOL 13,#12A	MPI CHARGER MODIFICATIONS FOR 600 MAH	03/27/91
GN SV		VOL 13,#13	029-176 WARRANTY FORM	04/16/91
GN SV		VOL 13,#13A	029-176 WARRANTY FORM ATTACHED	06/04/91
FM N9		VOL 13,#14	RANGR 16+ & FMD EE PROM TEMP PROBLEMS	04/24/91
QC04 S1		VOL 13,#15	GE-MARC V IRM RECEIVER MUTE Q2 CHANGED	05/01/91
TM		VOL 13,#16	TMX8712 L.O. RADIATION KIT - SPK9025	05/03/91
TM		VOL 13,#17	TMX8310 LOGIC BOARD WITHOUT PROM	05/10/91
S1		VOL 13,#18	GE-MARC IDA REPEATER CONTROL PANEL	05/06/91
MP		VOL 13,#19	MPI-II CG DECODE TIME	06/04/91
MP		VOL 13,#20	MPI-II TRANSMITTER AUDIO SENSITIVITY	06/04/91
PA PD TP		VOL 13,#21	MPD MPA SPK/MIC LOOSE LANYARD PIN	06/04/91
17 B3 S1 S3		VOL 13,#22	GE-MARC V REPEATER SYNTHESIZER LOCK	07/01/91
61 67 B3 S3		VOL 13,#23	MASTR-II LOW BAND RX SENSITIVITY	07/01/91
61 67 82 B3 S3		VOL 13,#24	MASTR-II TX AUDIO IC FAILURES 19A702868	07/01/91
S8		VOL 13,#25	S-825 PROG DEVIATION WITH V3.0	07/01/91
S8		VOL 13,#26	S-825 SIDETONE LEVEL	07/01/91
N8		VOL 13,#27	DELTA/RANGER STATION TONE CONTROL	07/01/91
N8		VOL 13,#28	DELTA/RANGER STA. RX SYNTHESIZER UNLOCK	07/01/91
MP		VOL 13,#29	MPI-II PROGRAMMING ERROR, SINGLE FREQ	07/01/91
MP		VOL 13,#30	MPI CARRY CASE & SQUELCH KNOB	08/01/91
MP		VOL 13,#31	MPI-II MICRO DEFECT, PROGRAMMING	08/05/91
MP		VOL 13,#32	MPI-II EAR MIC SECURITY OPT 1241 & 1244	08/05/91
MP PC P5		VOL 13,#33	MPI-II BAT. CURRENT DRAIN & FREQ SPREAD	08/05/91
MP		VOL 13,#34	MPI-II SYNTHESIZER OUT OF LOCK	10/14/91
B3		VOL 13,#35	MASTR-IIe DC CONTROL CURRENTS	10/14/91
TL		VOL 13,#36	MDS TL-800 TX POWER IN RECEIVE MODE	10/14/91
N9		VOL 13,#37	RANGER TOP COVER GASKET-RFI INTO CG MOD	10/14/91
PC		VOL 13,#38	PCS SPEAKER - REPLACED W/ MPA, SPK-9106	10/14/91
ML		VOL 13,#39	MLS-II SYNTHESIZER AT POWER UP - REV B	10/14/91
QC04 S1		VOL 13,#40	GE-MARC V PRODUCT SUPPORT - D&L	10/14/91
NP		VOL 13,#41	MVS CONTROL PANEL NPCP1D SUBSTITUTION	12/16/91
PD		VOL 13,#42	M-PD DATA LOSS-LITHIUM BATTERY CONTACT	12/16/91
H2		VOL 13,#43	RAPID CHARGER CONTACTS, MPD,MPA,PLS,TPX	12/16/91

MP		VOL 13,#44	MPI-II CG DECODE AT LOW TEMPERATURE	12/16/91
MP		VOL 13,#45	MPI-II UHF CG DECODE RESPONCE TIME	12/16/91
TL		VOL 13,#46	TL-800 MDS SERVICING INFORMATION	12/16/91
B3		VOL 13,#47	MASTR-IIe STANDBY CHARGER KILLS BATTERY	12/16/91
GN SV		VOL 12,#1	1989 TECH SVS. MEMO INDEX	01/03/90
TM		VOL 12,#2	TMX-8712 RF POWER & DESENSE IN DUPLEX	01/03/90
17 B3 S1 S3		VOL 12,#3	800 MHZ 24 V PA - TRANSIENT STABILITY	01/03/90
17 B3 S1 S3		VOL 12,#4	800 MHZ 24 V PA - NO POWER OUTPUT	01/03/90
17 B3 S1 S3		VOL 12,#5	800 MHZ EXCITER DRIVE INCREASE	01/03/90
TM		VOL 12,#6	TMX-8712 DECODE RELIABILITY & DIRECT	01/03/90
P5		VOL 12,#7	MPI - NEW BATTERY 19D900639	01/03/90
SV T2 TC		VOL 12,#8	GE MINI & MINI-II SERVICE	01/03/90
P5		VOL 12,#9	MPI SPEAKER MIC TX AUDIO	01/08/90
P5		VOL 12,#10	MPI - RF INTO TX MOD - C18	01/09/90
PC		VOL 12,#11	PCS PROGRAMMING CABLE - TQ3336	01/10/90
T4		VOL 12,#12	TRANSPACK - RINGING VOLUME	01/29/90
PD		VOL 12,#13	M-PD - SHIPPED WITH SYSTEM SOFTWARE	02/05/90
PD		VOL 12,#13A	M-PD - SOFTWARE	02/05/90
79 P9		VOL 12,#14	MPS - VEHICLE CHARGER FIT	02/05/90
TH		VOL 12,#15	CELLULAR HOTLINE UNLOCK CODE	04/04/90
PD		VOL 12,#16	MP-D VG AUDIO RESPONCE - SPK8910	04/29/90
S8		VOL 12,#17	S825 DUAL CONT. REV E -SEE TSM VOL13,#9	04/29/90
MC TM		VOL 12,#18	TMX-8712-85-83-8210 RFI GROUND CLIP	06/08/90
TM		VOL 12,#19	TMX-8712 MICRO FAILS-HORN ALERT SPIKES	06/08/90
PC		VOL 12,#20	PCS UDC COVER 19C851912P1	06/25/90
PC		VOL 12,#21	PCS / SPEAKER MIC, RFI INTO VCO, UNLOCK	08/29/90
PA PD		VOL 12,#22	M-PA MTL RF TEST ADAPTER/RX SENSITIVITY	08/12/90
PD		VOL 12,#23	M-PD LITHIUM BATTERY SOLDERABILITY	08/21/90
GN SV		VOL 12,#24	SOLDER RELATED TF CODES, 029-176	08/29/90
31 67 72 B3 S3		VOL 12,#25	FEED-THRU CAP 19C303426G1 SUBSTITUTION	08/30/90
TM		VOL 12,#26	TMX-8712 L.O. RADIATION REDUCED	09/13/90
17 B3 S3		VOL 12,#27	PST SYNTHESIZER CAUSING DATA LOSS	11/15/90
PC		VOL 12,#28	PCS CMOS EE-PROM RADIO MODIFICATIONS	11/13/90
PC		VOL 12,#28A	PCS CMOS EE-PROM RADIO MODIFICATIONS	12/20/90
PC		VOL 12,#29	PCS T-99 DECODE WITH DISTORTION/TIMING	11/13/90
PC		VOL 12,#30	PCS - RFI; RADIO FRONT COVER PLATING	11/13/90
17 B3 S1 S3		VOL 12,#31	GE-MARC REPEATER NOT PASSING HIGH TONES	11/14/90
GN SV		VOL 11,#1	1988 TECH SVS. MEMO INDEX	01/02/89
NP		VOL 11,#2	MVS STICKING CONTROL BUTTONS	01/02/89
CN NP		VOL 11,#3	MCS/MVS RADIO SOFTWARE UPDATES	01/03/89
CN NP		VOL 11,#4	MCS/MVS PC PROGRAMMING SOFTWARE UPDATE	01/06/89
61 65 67 B3 S3		VOL 11,#5	M-II VHF PA TRANSISTOR FAILURE	03/09/89
CN TM		VOL 11,#6	MCS CONTROL UNIT SUSCEPTIBLE TO RFI	04/13/89
CN NP		VOL 11,#7	MCS/MVS CG DECODER FALSING	04/13/89
PL		VOL 11,#8	PLS VHF SYNTHESIZER, POWER CONTROL & CG	04/14/89
PD PV		VOL 11,#9	M-PD & VOICE GUARD PROGRAMMING 6.25 KHZ	05/16/89
PD PV		VOL 11,#10	M-PD & VG SPEAKER MIC DISTORTED AUDIO	05/16/89
67 72 B3 S1 S3		VOL 11,#11	M-II STATION SECURIT TONE DETECTOR TEMP	07/13/89
RC		VOL 11,#12	RCN REMOTE DELAYED MICROPHONE AUDIO	07/13/89
TM		VOL 11,#13	TMX-8712 IMPROVE RX SENSITIVITY	07/13/89
T4		VOL 11,#14	CARFONE XR HANDS FREE PROGRAMING	07/18/89
N3 N9 QC05		VOL 11,#15	VG-9600 TX AUDIO IMPROVEMENT REV H	10/18/89
T8		VOL 11,#16	TRANSFONE FUSE AND WIRE SIZE INCREASE	09/29/89
PL		VOL 11,#17	PLS UHF VCO CG POWER SPKR MIC SPK8907	10/05/89
T4		VOL 11,#18	CARFONE 3W SYNTH UNLOCK-DEFECTIVE CAPS	10/18/89
T4		VOL 11,#18A	CARFONE DEFECTIVE CAPS MARKING CHANGED	02/12/90
T4		VOL 11,#19	CARFONE HANDS FREE AUDIO MUTE BY NOISE	11/02/89
T4		VOL 11,#19A	CARFONE HANDS FREE WARRANTY TIME LIMIT	02/12/90
PD PL TP		VOL 11,#20	M-PD PLS TPX RAPID CHARGER SHUT-OFF	11/01/89

P5 R2	VOL 11,#21	MPI DL100 Low TX power, ant T/R diode	11/14/89
P5 R2	VOL 11,#21A	MPI DL100 Low TX power, ant T/R diode	12/06/89
T3 T4 T8	Vol 11,#22	Carfone programming, A/B Select	11/14/89
T4 T8	VOL 11,#23	Carfone-Transpak D48 cause dead handset	11/21/89
GN	VOL 10,#1	1987 TECH SVS. MEMO INDEX	03/03/88
04	VOL 10,#2	PM-II Charging contacts	02/19/88
PD	VOL 10,#3	MPD SYSTEM and SCAN - Home Operation	02/19/88
TP	VOL 10,#4	TPX SOFT.Rev Min Audio,DTMF,DIRECT mode	06/09/88
TM 91	VOL 10,#5	TMX82-85 PROGRAMMING error 255	02/24/88
N5 ML CM TM	VOL 10,#6	Microphone gain & TX deviation	03/29/88
GN MP PL P9 TP	VOL 10,#7	NICKEL CADMIUM batteries, General hints	03/29/88
TM	VOL 10,#8	TMX 82/85 DIRECT mode & Horn Alert	10/04/88
TP H2	VOL 10,#9	TPX Audio bleed thru in vehicle charger	06/09/88
N7	VOL 10,#10	CLASSIC-II Clock crystal OSC radiation	04/13/88
PL	VOL 10,#11	PLS Software DTMF T99 HiLo PWR CG	04/12/88
T3	VOL 10,#12	CARFONE AUDIO VOICE & ALARM Level	05/13/88
S9	VOL 10,#13	S990 Failures	05/09/88
P2 P4 P9	VOL 10,#14	MPR/MPS/MPX Battery capacity increase	05/16/88
CN NP	VOL 10,#15	MCS/MVS PC Programming	06/07/88
T1	VOL 10,#16	GE-STAR CELLULAR ERROR 2 & ERROR 4	06/07/88
TM	VOL 10,#17	TMX 8210 8310 Upgrade 4X4 4 AREAS	10/04/88
TM	VOL 10,#18	TMX 82/85 I.F. OFFSET	10/04/88
CN	VOL 10,#19	MCS CG Disable with Hookswitch	07/07/88
PD PL TP	VOL 10,#20	MPD PLS TPX Dummy battery pack	08/01/88
ML	VOL 10,#21	MLS Intermittent Channel Guarw Decode	08/25/88
M6 N7 TM TP	VOL 10,#22	GE-MARC V/V.E CALL ORIG COLLECT Timing	10/04/88
CN NP TM	VOL 10,#23	MCS MVS TMX 82/85 Logic micro xtal	09/02/88
CN NP	VOL 10,#24	MCS, MVS VCO UNLOCK	09/07/88
CN NP	VOL 10,#24A	MCS MVS VCO UNLOCK E0 ERROR	09/22/88
ML	VOL 10,#25	MLS EE PROM Loosing memory	09/28/88
TM	VOL 10,#26	TMX 84/86 RADIO LOCK UP G10 Firmware	10/10/88
TM	VOL 10,#27	TMX 82/85 Rptr AQUISITION attack TIME	10/10/88
TM	VOL 10,#28	TMX 8210-8510 Microphone	10/12/88
M6	VOL 10,#29	C/C/C Firmware - Decoding higher tones	10/17/88
CN TM	VOL 10,#30	MCS TMX Q703 Blown on logic board	10/17/88
T1	VOL 10,#31	GE-STAR Firmware 19A703712 - Networking	10/24/88
T3	VOL 10,#32	CARFONE Firmware 19A704868G11 ERROR	10/25/88
T3	VOL 10,#33	CARFONE LD CELLS mod kit 19A705303	11/27/88
T3 T4	VOL 10,#34	CARFONE firware-LOCK UP & DISPLAY	10/28/88
NP PD TM T3 N9	VOL 10,#35	Service Depots & warranty	11/23/88
T3 T4	VOL 10,#36	ARA CARFONE service & warranty	12/02/88
GN	VOL 9, #1	1986 TECH SVC. MEMO INDEX	03/02/87
TM	VOL 9, #2	TMX82/85 LOGIC BD FAILURES-REV A	02/12/87
T6	VOL 9, #3	CELLULAR STATION TEST AND ALARM UNIT	01/28/87
P5	VOL 9, #4	MPI 2ND OSC CRYSTAL CUSHION	02/23/87
TM	VOL 9, #5	TMX84/86 DIGITAL SIGNAL MICRO 7720	02/24/87
91 N5 TM	VOL 9, #6	TMX82/85 & PSX200 EE-PROM PROGRAMMING	04/28/87
M1 M6 M7 N7	VOL 9, #7	C/C/C ICOM 19A701712 COMPENSATION SUBSTITUTION AND SETTING, ZT OPTION	04/28/87
91 PD	VOL 9, #8	M-PD SYSTEMS CG PROGRAMMING	05/18/87
ML	VOL 9, #9	MLS HIGH BAND RECEIVER TWEETS	06/04/87
ML	VOL 9, #10	MLS LOW BAND RECEIVER TWEETS	06/05/87
P5	VOL 9, #11	MPI T-99 MODULE 19D437921G2 SPK8710	06/08/87
91 PD	VOL 9, #12	M-PD PROGRAMMING & UDC OPTIONS INOP.	06/12/87
H2 PD	VOL 9, #13	M-PD RAPID CHARGER ERRATIC OPERATION	06/12/87
N7 SV T1 T3 TM	VOL 9, #14	ANTENNA RESTICTION-NON-METALIC VEH.	09/28/87
91 TM	VOL 9, #15	TMX84/86 REV A CHANGES & PROGRAMMING	07/15/87
T3	VOL 9, #16	CARFONE SOFTWARE FIX TO "NETWORKING"	10/23/87
T3	VOL 9, #16A	CARFONE SOFTWARE FIX TO "NETWORKING"	03/29/88

T3		VOL 9, #16B	CARFONE SOFTWARE FIX TO "NETWORKING"	11/11/88
17 67 B3 S1 S3		VOL 9, #17A	M-II 800 MHZ EXCITER PWR & RELIABILITY	11/13/87
T2		VOL 9, #18A	GE-MINI VEH. CHARGER ALTERNATOR WHINE	11/13/87
TM		VOL 9, #19	TMX-84/86 AUDIO QUALITY & FALSING	12/10/87
PD		VOL 9, #20	M-PD EXTERNAL ACCESSORIES INTERFACE	11/13/87
PD		VOL 9, #21	M-PD SERVICE AND TEST AIDS	11/13/87
04		VOL 9, #22	PORTAMOBILE-II CHARGER CONTACT SIZE	11/23/87
GN		VOL 8, #1	1985 TECH SVC. MEMO INDEX	01/21/86
N5		VOL 8, #2	VEHICLE START-UP RESET WATCHDOG TIMER	01/15/86
QC04		VOL 8, #3	GE-MARC V & V.E. SVS & ICS SUPT. PRGM	01/28/86
P5		VOL 8, #4	MPI ANTENNA ASSEMBLY	01/30/86
P5		VOL 8, #5	INSTALLATION OF MPI UHF PA XSISTORS	02/07/86
17 B3 S1 S3 T6		VOL 8, #6	PACKING OF PA ASSEMBLIES FOR SHIPPMENT	02/07/86
GN SV		VOL 8, #7	ENGR & MFG LOANER TRAINING TAPES	02/21/86
17 67 B3 S1 S3		VOL 8, #8	DUAL RACKED STATIONS WITH COMMON PWR	02/25/86
QC04		VOL 8, #9	INTERCONNECT SYSTEM GOES TO SLEEP	02/25/86
P5		VOL 8, #10	MPI RX OSCILLATOR START PROBLEMS	03/10/86
61 67 B3 S1 S3		VOL 8, #11	RF XSISTORS, REPLACEMENT & SUBSTITUTION	03/10/86
61 67 B3 S3		VOL 8, #12	M-II UHF PA, TROUBLESHOOT & REPAIR	03/07/86
TM		VOL 8, #13	MICROPHONE GAIN INCREASE FOR TMX	03/28/86
TM		VOL 8, #14	SPEAKER DAMAGED DURING INSTALLATION	03/28/86
N7 N5 N3 T3		VOL 8, #15	ACCESSORY-IGNITION SWITCH TERMINAL	05/02/86
T1 TM CM			NOT WHAT IT APPEARS	
T3		VOL 8, #16	HELPS AND SUGGESTIONS	05/02/86
P5 N3 T1 N5		VOL 8, #17	GOLD CONNECTORS	05/09/86
TM CM N5		VOL 8, #18	MICROPHONE SENS. IMPROVED TMX PHOENIX	06/06/86
P5 R2		VOL 8, #19	LOW POWER & POOR TUNING AT UHF	07/18/86
P5 R2		VOL 8, #20	RECEIVER FRONT-END OSCILATION AT UHF	07/18/86
T1 T3 T6		VOL 8, #21	CELLULAR STATIONS AND MOBILES	07/22/86
P5 R2		VOL 8, #22	GOLD/TIN CONTACTS	09/02/86
T3		VOL 8, #23	SOFTWARE UPGRADE - U4 TO 19A704868G5	09/04/86
T1 T2 T3		VOL 8, #24	TECHNICAL SERVICES MEMO'S	09/09/86
P9		VOL 8, #25	INCREASE MICROPHONE AUDIO GAIN	10/10/86
67 B3 S3		VOL 8, #26	MASTR II STATION-REPEAT AUDIO	10/03/86
N5		VOL 8, #27	PHOENIX STATION MIC SENSITIVITY	10/10/86
		VOL 8, #28	NEVER ISSUED	
32 67 72 S3		VOL 8, #29	HI POWER RF RELAY	10/10/86
61 65 67 B3 S3		VOL 8, #30	VHF M-II PA SUB. GUIDE	11/11/86
		VOL 8, #31	NEVER ISSUED	
		VOL 8, #32	NEVER ISSUED	
T6		VOL 8, #33	ST & SAT ADJ - GEN DET EXCEPT. RPTS	11/21/86
GN SV		VOL 8, #34	GLASS MOUNT ANTENNA INSTALL PRECAUTION	12/02/86
N5		VOL 8, #35	PHOENIX MICROPROCESSORS	12/04/86
P5		VOL 8, #36	MPI BATTERY PINS	12/12/86
GN		VOL 7, #1	INDEX - 1984 TECHNICAL SERVICE MEMOS	01/11/85
GN		VOL 7, #1A	INDEX - 1984 TECHNICAL SERVICE MEMOS	02/22/85
T1		VOL 7, #2	NOISE ON 7.5 VOLT REGULATOR WHEN HOT	01/18/85
91 N5 S9		VOL 7, #3	PROGRAMMER ERROR CODES	01/18/85
N3 N5		VOL 7, #4	RECEIVER TWEETS - DELTA & PHOENIX	01/18/85
N3 N5		VOL 7, #5	VCO TUNING - DELTA & PHOENIX	01/25/85
S9		VOL 7, #6	S950 SCRAMBLED DATA DURING OPERATION	01/25/85
91		VOL 7, #7	PANASONIC SERVICE FOR TQ2310 PROGRAMMER	01/25/85
N3		VOL 7, #8	COLD TEMP OSC FAILURES-DELTA LOW BAND	01/25/85
P5		VOL 7, #9	CHANNEL GUARD MODULES-50% FAILURES?	02/01/85
P5		VOL 7, #10	MPI VHF OSC COMP IN DEALER RADIOS	02/01/85
91		VOL 7, #11	TQ2310 ACC, CABLES&PROMS(see VOL 7 #40)	03/08/85
P7		VOL 7, #12	GE-MARC PORTABLES INTERMITTENTLY KEYING	03/22/85
N5		VOL 7, #13	NEW MICRO FIX SCAN AND CG PROBLEMS	04/04/85
N5		VOL 7, #14	NEC MICROCOMPUTERS - 19A703754G4	04/04/85

N5		VOL 7, #15	RAM MEMORY LOSS WHEN STARTING VEHICLE	03/22/85
N5		VOL 7, #16	VOL/ON/OFF SWITCH SHIELD	04/04/85
GN N3 N5 N7 P7		VOL 7, #17	ENGINEERING VIDEO TRAINING TAPES	04/05/85
QC04 P9 S9 SV				
GN N3 N5 N7 P7		VOL 7, #17A	ENGINEERING VIDEO TRAINING TAPES	05/06/85
QC04 P9 S9 SV				
T1 T3		VOL 7, #18	SAT AND ST LEVEL SETTINGS	04/19/85
SV T1 T3		VOL 7, #19	CELLULAR MOBILE CHECKOUT PROCEDURE	05/01/85
SV T1 T3		VOL 7, #19A	CELLULAR MOBILE CHECKOUT PROCEDURE	09/09/86
17 22 61 65		VOL 7, #20	MASTR-II - LOW AUDIO IFAS BOARD	04/26/85
67 70 B3 S3				
61 65 67 B3 S3		VOL 7, #21	MASTR-II PLL EXCITER WON'T HOLD LOCK	05/10/85
P5		VOL 7, #22	MPI INTERMITTENT SPEAKER MICROPHONE	05/10/85
P5		VOL 7, #22A	MPI INTERMITTENT SPEAKER MICROPHONE	06/23/86
91 N3 N5		VOL 7, #23	4EX22A10 EE-PROM PROGRAMMER MANUALS	05/10/85
M1 M6 M7		VOL 7, #24	C/C/C LOGIC BOARD HYBRID FAILURE	05/24/85
N3		VOL 7, #25	DELTA UHF TRANSMITTED ALTERNATOR WHINE	05/24/85
N3 N8		VOL 7, #26	DELTA STATION - NO SPEAKER AUDIO	05/24/85
N3 N8		VOL 7, #27	DELTA STA-SCAN MOD FOR FIXED PRIORITY	07/24/85
N3 N8		VOL 7, #27A	DELTA STA-SCAN MOD FOR FIXED PRIORITY	08/30/85
S9		VOL 7, #28	S950 PROGRAMMING	05/24/85
N7 TM T1 T3		VOL 7, #29	HANDSET MOUNTING - HORIZONTAL	05/31/85
P4		VOL 7, #30	MPX 800 MHz R.F. INTERFERENCE	06/07/85
P4		VOL 7, #30A	MPX 800 MHz R.F. INTERFERENCE	07/19/85
P7		VOL 7, #31	GE-MARC PORTABLE KEYBOARD LIGHT	07/19/85
GN SV		VOL 7, #32	HANDLING OF STATIC SENS PTS AND ASSY	07/19/85
N7		VOL 7, #33	CL-II LOCK-UP AND/OR LOSS OF AUDIO	08/16/85
N7		VOL 7, #34	CL-II EARPIECE AUDIO LEVEL	08/16/85
N7		VOL 7, #35	CLASSIC-II PROGRAMMING	07/26/85
SV		VOL 7, #36	ATT/BELL TELEPHONE LINE SPECIFICATIONS	07/26/85
T1		VOL 7, #37	GE-STAR SOFTWARE 19A703712G8 TO G15	08/30/85
05 06 13		VOL 7, #38	EX-II VERSATONE CG FAILS TO MUTE	08/16/85
N3		VOL 7, #39	DELTA S - PTT FAILS TO RELEASE	08/16/85
SV 91 M6 N3 N5		VOL 7, #40	TQ2310 ACC, CABLES & PROMS	08/16/85
N5		VOL 7, #41	PHOENIX SCAN - MICRO REPLACEMENT	08/16/85
N3		VOL 7, #42	DELTA LB - VCO FAILS TO LOCK	08/16/85
N3 N5		VOL 7, #43	PHOENIX & DELTA - MICRO-COMPUTERS	08/16/85
N3 N5 S9		VOL 7, #44	DELTA, PHOENIX - EE PROMS PROGRAMMED	08/16/85
17 S1		VOL 7, #45	GE-MARC REPEATER CONTROL MUTE INHIBIT	08/23/85
P5		VOL 7, #46	MPI ON/OFF VOLUME POT - SPK8512	08/23/85
M1 N7		VOL 7, #47	CLASSIC DUPLEX DESENSE NOISE	09/05/85
T1		VOL 7, #48	GE*STAR NO AUDIO/DISTORTED AUDIO	09/23/85
GN		VOL 7, #49	TECHNICAL SERVICE MEMO NUMBERING SYSTEM	08/30/85
N3		VOL 7, #50	DELTA LB - VCO CAPACITOR POLARITY	08/30/85
N5		VOL 7, #51	DELTA STYLE MICROPHONES FOR PHOENIX	09/13/85
GN		VOL 7, #52	LIFETIME F.C.C. LICENSE	09/13/85
N3		VOL 7, #53	DELTA LB VCO FAILS TO LOCK	09/13/85
N3		VOL 7, #54	DELTA-S WATCHDOG TIMER STABILITY	09/13/85
S9		VOL 7, #55	S950 RESET CIRCUIT ON VEHICLE START UP	09/13/85
33 M6		VOL 7, #56	GE-STAR (ON CORONA) ID KEEPS REPEATING	10/31/85
SV T2		VOL 7, #57	GE-MINI SERVICE INFORMATION	09/20/85
T1 T3 T6		VOL 7, #58	SERVICE INFORMATION GATHERING	10/25/85
91 P7		VOL 7, #59	GE-MARC V PORTABLE PROGRAMMING	11/11/85
N7		VOL 7, #60	CLASSIC-II LOSS OF RECEIVE AUDIO	11/14/85
P5		VOL 7, #61	MPI VOLTAGE REGULATOR	11/14/85
M1 M6 M7		VOL 7, #62	C/C/C MICROPROCESSOR PTT PROTECTION	11/11/85
P5		VOL 7, #63	MPI CHANNEL GUARD - SHOCK DAMAGE	12/03/85
T1		VOL 7, #64	GE*STAR SAT SENSITIVITY IMPROVEMENT	12/18/85
GN		VOL 6, #1	1983 TECH SVC MEMO INDEX	02/03/84
N3 N5		VOL 6, #2	PHOENIX-S & DELTA-S EE PROMS	02/03/84

91 N3 N5	VOL 6, #3	TQ2310 IO ERROR 127 - CABLE CROSSTALK	02/03/84
91 N3 N5	VOL 6, #4	4EX22A10-LOSS OF PRE-PROGRAMMED MEMORY	02/03/84
M1 M6 M7	VOL 6, #5	C/C/C BUSY TONE DROPOUT TIME CHANGED	02/17/84
M1 M6 M7 N7	VOL 6, #6	C/C/C MICROPHONICS - VCO & ICOM	02/17/84
M1 M7	VOL 6, #7	CLASSIC DTMF ENCODER AND KEY PAD	02/17/84
79 P2 P4	VOL 6, #8	MPR/MPX VEHICULAR CHGR RETROFIT KITS	03/02/84
17 61 67 70 S3	VOL 6, #9	MII PROGRAMMABLE CG OFF FREQUENCY	03/02/84
05 06 08 13 21	VOL 6, #10	RF CASTING INT. RX SENS-TUNING THREADS	03/02/84
65 67 B3 S3			
17 S1 S3	VOL 6, #11	90 W 800 MHZ SOLID STATE PA REWORK	03/02/84
P5	VOL 6, #12	MPI DESK CHARGER-INTERF W/ FM BROADCAST	04/24/84
QC04	VOL 6, #13	CPU PORT PROTECTION FOR ZETRON OVERDIAL	03/30/84
67 S3	VOL 6, #14	DIGITAL DECODER IN REPEATER FALSING	03/30/84
61 65 67 B3 S3	VOL 6, #15	MASTR-II-SPURIOUS FROM PLL EXCITER	03/30/84
M1 M6 M7	VOL 6, #16	GE-MARC V C/C/C LOGIC BD CPU CLOCKFAILS	04/27/84
17 S1	VOL 6, #17	GE-MARC REPTR-BUSY TONE FILTER OFF FREQ	04/27/84
M6 M7 M1	VOL 6, #18	C/C/C SYNTH. VCO LOCK VOLTAGE CHANGE	04/27/84
N5	VOL 6, #19	PHOENIX S/SX MICROPHONE - 19C850857G2	04/27/84
N3 N5	VOL 6, #20	PHOENIX/DELTA 4EX22A10 PROGRAM MANUALS	04/27/84
N5	VOL 6, #21	PHOENIX-SX FACE PLATE PART NUMBERS	04/27/84
61 67 S3 N3 N5	VOL 6, #22	DIGITAL CHANNEL GUARD CODE LIST	04/27/84
67 S3	VOL 6, #23	INTERCOMM BOARD GENERATING RFI	05/18/84
17 61 67 B3 S3	VOL 6, #24	MASTR-II-VOICE BLOCKING PROGRAMMABLE CG	05/18/84
M1	VOL 6, #25	CLASSIC RM RX SENS IMPROVED BY LOV REG	05/18/84
M6 M7	VOL 6, #26	C/C/C - BAD POTS 19A700185P4 &5	05/18/84
06 28 61 65	VOL 6, #27	4EJ18A10 DIGITAL DECODER FALSE RESET ON HORN BLOW	05/18/84
08 15	VOL 6, #28	CMVP VOLUME CONTROL - 5496870P35	05/18/84
N3	VOL 6, #29	DELTA-S BINARY CONVERTER-SQUELCH POP	05/25/84
N5	VOL 6, #30	PHOENIX SX SCAN - TX HUM & NOISE	05/25/84
N5	VOL 6, #31	PHOENIX SX SCAN - CG NOT UNSQUELCHING	05/25/84
N3 N5	VOL 6, #32	DELTA/PHOENIX - VEHICLE START-UP RESET	05/25/84
N3 N5	VOL 6, #32A	DELTA/PHOENIX - VEHICLE START-UP RESET	11/09/84
N3	VOL 6, #33	DELTA-S - SUSCEPTIBILITY TO EXTERNAL RF	05/25/84
M6 M7 M1	VOL 6, #34	C/C/C ALIGN OF SYNTH L2611 > VOL 6,#68	05/25/84
N3	VOL 6, #35	DELTA-S - MICROCOMPUTER TESTS	06/01/84
N3	VOL 6, #36	DELTA-S PWR/CONT CABLE CONNECTOR SCREW	06/01/84
79 P2 P4	VOL 6, #37	MPR/MPX 3 HOUR MULTICHARGER	06/01/84
N5	VOL 6, #38	PHOENIX-SX SCAN - PROGRAMMING	06/01/84
61 65	VOL 6, #39	C500 PSLM SELECTING TWO ICOMS	06/01/84
61 65	VOL 6, #39A	C500 PSLM SELECTING TWO ICOMS	11/09/84
T1	VOL 6, #40	GE-STAR MEMORY LOSS-IGNITION TURN ON	06/01/84
N3	VOL 6, #41	DELTA-S EXCITER & TX METERING LOW	06/27/84
M1 M6 M7	VOL 6, #42	C/C/C FREQ PROM RANDOMIZATION	06/27/84
M1 M7	VOL 6, #43	CLASSIC PUSH BUTTON VOL-AREA-CLEAR	06/27/84
N5	VOL 6, #44	PHOENIX-S UHF RX SENSITIVITY DEGRADE	07/27/84
M1 M5 M6 M7 N7	VOL 6, #45	C/C/C SOLDERING ICOMS TO SYNTHESIZER BD	07/27/84
M1 M6 M7 N7	VOL 6, #46	C/C/C ALTERNATOR WHINE	07/27/84
GN M6 N7 SV T3	VOL 6, #47	CRIMP COAX CONNECTORS & TOOLS	07/27/84
M1	VOL 6, #48	CLASSIC-RM AUDIO - LOGIC BD 19D900253G5	07/27/84
M1 M6 M7	VOL 6, #49	C/C/C POT CHANGE - OLD 19A700185	07/27/84
P5	VOL 6, #50	MPI MULTI-CHARGER FAILURES-XFMR CHANGE	07/27/84
M1	VOL 6, #51	CLASSIC-RM DUPLEX PROGRAMMING ERROR	09/07/84
M1	VOL 6, #51A	CLASSIC-RM DUPLEX PROGRAMMING ERROR	10/26/84
67 B3 S3	VOL 6, #52	M-II DC REMOTE-KEYS WITH LOCAL F1/F2	09/07/84
06 11 61 65	VOL 6, #53	C500 PSLM DIODES CAUSE RX SPURIOUS	09/07/84
06 07 13 61 65	VOL 6, #54	C800 CONTROL - MULTI-TONE CG DISTORTION	09/07/84
M1 M7	VOL 6, #55	CLASSIC HANDSET EARPIECE & MIC LEVEL	09/07/84
P5	VOL 6, #56	MPI XTALS - TOL AND DRIVE SPECS	09/07/84
P5	VOL 6, #57	MPI POPS & SQUEAKS DURING TX	09/20/84
P5	VOL 6, #57A	MPI POPS & SQUEAKS DURING TX	10/26/84

T1		VOL 6, #58	GE*STAR DUAL CONTROL ON-HOOK SPEAKER	09/28/84
T1		VOL 6, #59	GE*STAR UNLOCK CODE - LOCK OUT TIMER	09/28/84
T1		VOL 6, #60	GE*STAR CALL TIMER - DUAL CONTROL	09/28/84
17 67 S1 B3 S3		VOL 6, #61	800 MHZ 90W SOLID STATE PA'S	09/28/84
79 P2 P4		VOL 6, #62	MPR/MPX ONE HOUR CHARGER LATCH UP	09/28/84
M1 M5 M6 M7 N7		VOL 6, #63	C/C/C RX AUDIO RESPONCE NOISE REDUCTION	09/28/84
T1		VOL 6, #64	GE*STAR HORN RELAY INSTALLATION	09/28/84
T1		VOL 6, #65	GE*STAR FAILURES - UNAPPROVED NAMS	09/28/84
T1 T3		VOL 6, #66	GE*STAR IGNITION TURN-OFF PROBLEMS	09/28/84
M1		VOL 6, #67	GE*STAR BATTERY CONNECTION PROBLEMS	09/28/84
M1 M6 M7		VOL 6, #68	C/C/C TUNING OF SYNTH BD L2611	09/28/84
GN P2 P4 P5 P6		VOL 6, #69	NICKEL CADMIUM BATTERIES /see VOL 10,#7	09/28/84
P5		VOL 6, #70	MPI DESK CHARGER MODIFICATION 4W BATT	09/28/84
T1		VOL 6, #71	GE-STAR CALL FORWARDING DIFFICULTY	10/26/84
N3 N5		VOL 6, #72	DELTA-PHOENIX WHISKERS IN ZINC CASTINGS	10/26/84
17 QC04 S1		VOL 6, #73	GE-MARC V ICS DUPLEX MODIFICATION	10/26/84
M6 M7		VOL 6, #74	C/C/C MONITOR RADIO - NOISE SQUELCH	10/26/84
17 QC04 S1		VOL 6, #75	GE-MARC V ICS RESTRICTION PROGRAMMING	10/26/84
N3		VOL 6, #76	DELTA-S MEMORY LOSS	10/26/84
N3		VOL 6, #76A	DELTA-S MEMORY LOSS	01/18/85
91 M6 M7 M1 T1		VOL 6, #77	BI-POLAR ADAPTER TQ2324 PROBLEMS	10/26/84
T1		VOL 6, #78	GE*STAR SUPPORT	10/26/84
61 65 67 S1 S3		VOL 6, #79	MASTR-II NEW AUDIO HYBRID	10/26/84
06 08 61 67		VOL 6, #80	UHF PA OSCILLATIONS-19C331218G2 PA BD.	11/09/84
M1		VOL 6, #81	CLASSIC-RM DUPLEX "DPX" ICOM	11/09/84
17 67 S1 B3 S3		VOL 6, #82	MASTR-II REPT - DISTORTED REPEAT AUDIO	11/09/84
17 67		VOL 6, #83	MASTR-II SHOCK HAZARD ON METER PANEL	11/09/84
06 07 61 65		VOL 6, #84	C800/C900 VOLUME CONTROL REPLACEMENT	11/09/84
M2 M6 N7 QC04		VOL 6, #85	GE-MARC V MISSING & FALSE CALLS	11/09/84
		VOL 6, #86	NEVER ISSUED	
M1		VOL 6, #87	CLASSIC DUPLEX-MINIMIZE DESENSING	12/07/84
T1 T3		VOL 6, #88	CELLULAR HANDSET ERROR 4	12/07/84
T1 T3		VOL 6, #89	CELLULAR HANDSET AUDIO FEEDBACK	12/07/84
T1		VOL 6, #90	CELLULAR INTERFACE BOX TQ2334	12/07/84
GN		VOL 5, #1	1982 TECH SVC MEMO INDEX	01/28/83
79 P2 P4		VOL 5, #2	MPR/MPX VEH. CHARGER ADJ. PROCEDURE	01/29/83
N3		VOL 5, #3	DELTA CRYSTALS	01/29/83
13 61 67 B3 S3		VOL 5, #4	UHF RF TRANSISTOR 19A134242P1 SUB.	02/11/83
G5		VOL 5, #5	GE MARC 500 FUSING	02/11/83
17 67 B3 S1 S3		VOL 5, #6	800 MHZ. PA-ADDING TUNING CAPACITORS	02/11/83
17 67 B3 S1 S3		VOL 5, #6A	800 MHZ. PA-ADDING TUNING CAPACITORS	03/25/83
17 67 B3 S1 S3		VOL 5, #7	MASTR-II MULTI RACK STATIONS, FUSING	02/11/83
52 71 P6		VOL 5, #8	PE MULTI-TONE CG PROM ORDER NO.	03/25/83
52 71 P6		VOL 5, #9	MPE FIELD RETROFIT KITS	03/25/83
52 71 P6		VOL 5, #10	MPE MICROPHONE RF BYPASS	03/25/83
17 67 B3 S3		VOL 5, #11	MASTR-II RPTR - MUTES W/PROGRAMMABLE CG	04/22/83
67 S3		VOL 5, #12	MASTR-II MID BAND EXCITER SPURIOUS	04/22/83
P2 P4		VOL 5, #13	MPR/MPX FLEX CIRCUIT BREAKAGE	04/22/83
P2 P4		VOL 5, #13A	MPR/MPX FLEX CIRCUIT BREAKAGE	05/27/83
82		VOL 5, #14	VEHICULAR REPEATER SQUELCH	06/03/83
17 67 B3 S3		VOL 5, #15	MASTR-II ERRATIC SECURIT TONE OPERATION	06/03/83
61 65 67 B3 S3		VOL 5, #16	MASTR-II PROGRAMMABLE CG DISTORTION	06/03/83
M6 M1 M7 N7		VOL 5, #17	C/C/C - REDUCE MULTIPATH NOISE	06/18/83
M1 M7		VOL 5, #18	CLASSIC DTMF SWITCH PAD FAILURES	06/18/83
QC04		VOL 5, #19	GE-MARC IRM DIAL TONE DETECTOR PROBE	06/18/83
P2 P4		VOL 5, #20	MPX UHF SYSTEM BOARD RFI MODIFICATION	06/17/83
M6 M1 M7 N7		VOL 5, #21	C/C/C 800 MHZ PA MODULE 19A143904	06/24/83
M6 M1 M7		VOL 5, #22	C/C/C RF PROM SUB. FOR SERVICING	06/24/83
N5		VOL 5, #23	PHOENIX-XTAL INTERMIT. LOSS OF RX SENS.	06/24/83
P2 P4		VOL 5, #24	MPR/MPX UHF OFFSET OSC PART NUMBERS	07/22/83

13 61 65 67 S3	VOL 5, #25	MASTR-II VHF BURNOUT 429709G3 PWR CONT	08/19/83
13 61 65 67 S3	VOL 5, #25A	<u>MASTR-II VHF BURNOUT 429709G3 PWR CONT</u>	03/02/84
M1 M6 M7	VOL 5, #26	<u>C/C/C IF OFFSET INTERFERENCE</u>	08/05/83
M1 M6 M7 N7	VOL 5, #27	<u>CLASSIC-RM, AMPLITUDE MODULATION</u>	08/12/83
17 61 65 67 S3	VOL 5, #28	<u>MASTR-II PROGRAMMABLE CG POOR SENS.</u>	08/12/83
P2 P4 P5	VOL 5, #29	<u>MPI/MPR/MPX -STAYING KEYED BROKE XTAL</u>	08/29/83
N5	VOL 5, #30	<u>PHOENIX S/SX PROGRAMMABLE STE</u>	08/29/83
N5	VOL 5, #31	<u>PHOENIX S/SX VHF VCO UNLOCK 170-174 MHZ</u>	08/29/83
N5	VOL 5, #32	<u>PHOENIX S/SX DIGITAL CG ADJUSTMENT</u>	08/29/83
C4 N3	VOL 5, #33	<u>S600 CONTROL LBI-31231A ERROR</u>	08/29/83
N5	VOL 5, #34	<u>PHOENIX S/SX W/DC REMOTE RX MUTE</u>	08/29/83
52 71 P6	VOL 5, #35	<u>MPE/PY PTT STICKING - STAYS KEYED</u>	08/29/83
P5	VOL 5, #36	<u>MPI RADIOS (BATTERY) CONTACT-PLATING</u>	09/09/83
17 QC04 S1	VOL 5, #37	<u>GE-MARC V ICS PHONE LINES UNTANGLED</u>	09/02/83
GN M6 M7 SV TM	VOL 5, #38	<u>C/C/C ADD-ON OPTIONS ARE PROBLEM</u>	09/02/83
17 67 M2 S1 S2	VOL 5, #39	<u>VERSATONE NETWORKS</u>	09/09/83
P8	VOL 5, #40	<u>EXECUTIVE II PAGER SUPPORT PROGRAM</u>	09/09/83
M5	VOL 5, #41	<u>C-II 800 MHz ICOM 19A701712G1 NLA</u>	09/09/83
M1 M6 M7	VOL 5, #42	<u>C/C/C ICOM 19A701712G2 NLA</u>	09/09/83
GN 17 M5 M6 SV	VOL 5, #43	<u>800 MHz OSC STABILITY - SERVICING</u>	10/23/83
17 67 S1 S3	VOL 5, #44	<u>MASTR-II 800 MHZ 90 WATT PA</u>	10/14/83
GN SV	VOL 5, #45	<u>LP-GAS POWERED VEHICLES - NEW STANDARDS</u>	10/14/83
61 65 67 B3 S3	VOL 5, #46	<u>MASTR-II VHF PA VSWR ADJUSTMENT</u>	12/19/83
QC01	VOL 5, #47	<u>2500 CONSOLE - PTT SWITCH ASSEMBLY</u>	10/28/83
07 M3 N4	VOL 5, #48	<u>C800/900 CONTROL ON DELTA WITH PSLM</u>	10/28/83
07 M3 N4	VOL 5, #48A	<u>C800/900 CONTROL ON DELTA WITH PSLM</u>	12/16/83
GE SV 06 61 67	VOL 5, #49	<u>INTERMIT. CONTACTS-FRETTING CORROSION</u>	11/18/83
N5	VOL 5, #50	<u>PHOENIX-SX MICRO STABILITY DURING START</u>	12/16/83
38 91 N3 N5	VOL 5, #51	<u>4EX22A10 PROGRAMMER BOOKS</u>	12/16/83
GN SV	VOL 5, #52	<u>ALTERNATOR WHINE FILTERS</u>	12/16/83
17 67 S1 S3	VOL 5, #53	<u>800 MHZ 90W SOLID-STATE PAs</u>	12/23/83
67	VOL 4, #1	<u>MASTR-II 75 & 100 W UHF L-PASS SHORT</u>	02/05/82
10	VOL 4, #2	<u>AHO PAGER BATTERY DRAIN EXCESSIVE</u>	02/05/82
67	VOL 4, #3	<u>MASTR-II SECURIT BD - C30 IN CKT WRONG</u>	02/05/82
M4	VOL 4, #4	<u>DELTA XTAL - XTAL SOCKET REPLACEMENT</u>	02/05/82
M4	VOL 4, #5	<u>DELTA - POSITIVE GROUND INSTALLATION</u>	02/05/82
GN	VOL 4, #6	<u>1981 TECHNICAL SERVICE MEMO INDEX</u>	02/05/82
M4	VOL 4, #7	<u>DELTA MAINTENANCE MANUALS</u>	02/26/82
M1 M6 M7	VOL 4, #8	<u>C/C/C LOW TONE DEVIATION</u>	02/26/82
GN	VOL 4, #9	<u>STATIC IN THE OFFICE</u>	02/26/87
08 M5	VOL 4, #10	<u>CMVP & C-II REMOTE WITH TX NOISE</u>	02/26/82
67 M4	VOL 4, #11	<u>M-II & DELTA MULTI-TONE CG DE-EMPHASIS</u>	02/26/82
52 71 P2 P4 P5	VOL 4, #12	<u>INTRINSICALLY SAFE PORTABLES RADIO SVC</u>	03/12/82
P2 P4	VOL 4, #13	<u>MPR/MPX LED FAILURES</u>	03/12/82
64	VOL 4, #14	<u>MASTR CONTROLLER DC CONTROL BD</u>	03/12/82
18 C1	VOL 4, #15	<u>MCS CONTROL HEAD COVER SCREWS</u>	04/02/82
13 61 65 67	VOL 4, #16	<u>MASTR-II VHF TRANSMITTER VSWR</u>	04/02/82
P2 P4	VOL 4, #17	<u>MPR & MPX ACCESSORY PLATE</u>	04/09/82
P2 P4	VOL 4, #18	<u>MPR/MPX TEST ADAPTOR 4EXA2A11</u>	04/02/82
P2	VOL 4, #19	<u>MPR VEHICULAR CHARGER REG Q1 FAILURE</u>	04/02/82
16 52 71	VOL 4, #20	<u>PE & PY FRONT END MOUNTING SCREWS</u>	04/02/82
GN SV	VOL 4, #21	<u>CONDUCTIVE GREASE SS2218</u>	04/02/82
52 71	VOL 4, #22	<u>PE & PY PUSH-TO-TALK SWITCH</u>	04/09/82
18 C1	VOL 4, #23	<u>MCS CONTROL UNIT - LOW VOLTAGE</u>	04/09/84
M4	VOL 4, #24	<u>DELTA FREQUENCY DRIFT</u>	05/21/82
GN SV M6 M7 M1	VOL 4, #25	<u>GE-MARC V MAINTENANCE PROGRAM</u>	05/21/82
GN 17 S1 M2 N7	VOL 4, #26	<u>800 MHZ WITCH CRAFT</u>	05/21/82
GN SV N5 N3 TM	VOL 4, #27	<u>CHIP COMPONENT REPLACEMENT</u>	05/21/82
GN	VOL 4, #28	<u>RANGE CALCULATDR ECR 16F</u>	05/21/82
M5 M6 M7 M1	VOL 4, #29	<u>C/C/C 800 MHZ MICROPHONICS</u>	05/21/82

M2 S2	VOL 4, #30	GE-MARC EX- II '913 LOGIC BOARD	05/21/82
P2 P4	VOL 4, #31	MPR/MPX BATTERY FUSE CHANGE	05/21/82
P2 P4	VOL 4, #32	MPR/MPX BATTERY FUSE BLOWN	05/21/82
52 71 P2 P4	VOL 4, #33	SPEAKER-MIC PTT OPTION INTERMITTENT	05/28/82
M2 S2	VOL 4, #34	GE-MARC V EX-II SYNTHESIZER	05/28/82
QC04 M6 N7 TM	VOL 4, #35	GE-MARC V TONE SIGNALLING - A RESOURCE	05/28/82
07	VOL 4, #36	C800/900 PSLM vs DUAL CONTROL	05/28/82
06 11 33 61 65	VOL 4, #37	C-500 T90 ENCODER DISTORTION	08/20/82
P4	VOL 4, #38	MPX DEAD BATTERY INDICATOR	08/20/82
07 C4 M4 N3	VOL 4, #39	DELTA C800/900 PSLM C600 POTPOURRI	08/20/82
07 C4 M4 N3	VOL 4, #39A	DELTA C800/900 PSLM C600 POTPOURRI	10/29/82
		MIS-MARKED AS 40 REV A	
GN 08 67 VEND	SPECIAL	TELEPHONE INTERCONNECT SERVICING	08/20/82
64	VOL 4, #40	CONTROLLER CG MONITOR INTERMITTENT	10/01/82
07 C4 M4 N3	VOL 4, #40A*	DELTA C800/900 PSLM C600 POTPOURRI	10/29/82
	*EDITION MARKED VOL 4, #40A,	SHOULD HAVE BEEN MARKED VOL 4, 39A	
17 67 QC04	VOL 4, #41	800 MHZ 35 W PA POWER OUTPUT UNSTABLE	10/01/82
17 67 QC04	VOL 4, #41A	800 MHZ 35 W PA POWER OUTPUT UNSTABLE	11/05/82
91 VEND	VOL 4, #42	TQ2301 PROM PROGRAMMER KONTRON MPP80S	10/01/82
M5	VOL 4, #43	C-II RX SPURS - HIGH ACTIVITY XTALS	10/01/82
G5	VOL 4, #44	GE-MARC 500 TERMINAL PTT RELAY	10/01/82
79 P2 P4	VOL 4, #45	MPR/MPX RAPID-1 MULTI-CHARGER WATCHDOG	11/01/82
17 67	VOL 4, #46	800 MHZ 90 W PA TEST PROCEEDURE	11/01/82
61 65 67	VOL 4, #47	MASTR-II ICOMS FALLING OUT	11/05/82
M4	VOL 4, #48	DELTA CARRIER CONTROL TIMER ALERT	11/05/82
M6 M7 M1	VOL 4, #49	C/C/C FREQUEWCY PROMS-SEE TSM VOL 6 #42	12/03/82
P2 P4	VOL 4, #50	MPR/MPX TORX SCREWS FOR COVERS - ST0716	12/03/82
P2 P4	VOL 4, #51	MPR/MPX RADIO BASEPLATE CHANGE	12/03/82
67	VOL 4, #52	200 W UHF TUBED PA TUNING - 19D423414	12/03/82
GN 62 64 67 72	VOL 4, #53	AUDIO COMPRESSOR DISTORTION	12/10/82
17 67 S1	VOL 4, #54	800 MHZ MASTR-II PA CURRENT	12/10/82
61 65 67	VOL 4, #55	MASTR-II LB 100 W POWER CONTROL OSC	12/22/82
VEND 91	VOL 4, #56	PROM PROGRAMMER - RIVERLAKES SYSTEMS	12/22/82
M2	VOL 3, #1	FALSING IN GE-MARC V TRUNKED SYSTEMS	01/22/81
17 S1	VOL 3, #2	ACQUISITION TONE TIMING INCORRECT	02/17/81
17 S1	VOL 3, #3	REPEATER LOCK-UP, 800 MHZ	01/23/81
04 52 71	VOL 3, #4	PORTA-MOBILE II PE VEHICULAR CHARGER	02/20/81
16 52 71	VOL 3, #5	PERSONAL PORTABLE PTT RELAY FAILURE	02/20/81
17 67 72	VOL 3, #6	SECURIT-TONE LIMITED AUDIO	02/13/81
05 06 08 15	VOL 3, #7	INTERMITTENT LOSS OF RCVR SENSITIVITY	02/13/81
61 65 67			
28	VOL 3, #8	4EJ18 DIGITAL DECODER FALSING	02/13/81
72 67	VOL 3, #9	FOUR FREQUENCY TONE CONTROLLING	04/01/81
72 67	VOL 3, #9A	FOUR FREQUENCY TONE CONTROLLING	06/01/81
M2 S2	VOL 3, #10	SYNTHESIZER LOCK TIME-GE-MARC V EX-II	02/17/81
M2 S2	VOL 3, #11	SYNTHESIZER PLL LOCK VOLTAGE SETTING	02/18/81
M2 S2	VOL 3, #12	AREA PROM FAILURE - GE-MARC V EX-II	02/18/81
M2 S2	VOL 3, #13	SYNTHESIZER SHORTS - GE-MARC V EX-II	02/18/81
M2 S2	VOL 3, #14	SYNTHESIZER MICHOPHONICS-GE-MARC EX-II	02/19/81
M2 S2	VOL 3, #15	SYNTHESIZER-LOOSE SCREWS-GE-MARC EX-II	02/19/81
M2 S2	VOL 3, #16	HOOKSWITCH/PTT OPERATION ERRATIC	02/19/81
M2 S2	VOL 3, #17	TONE DETECT DELAY TOO SHORT	02/19/81
17 M2 S1 S2	VOL 3, #18	800 MHZ PA POWER FLUCTUATIONS	02/19/81
17 M2 S1 S2	VOL 3, #19	800 MHZ, PA CAPACITOR FAILURE	02/19/81
17 67 S1	VOL 3, #20	STATION KEYS SELF ON THE AIR & LOCKS	02/19/81
M2 S2	VOL 3, #21	FALSING CAUSED BY LOGIC BD JUMPERS	02/19/81
M2 S2	VOL 3, #22	SYNTH LOCK AT POWER UP & TEMP EXTREME	02/19/81
M2 S2	VOL 3, #23	SYNTH. LOGIC-('918) MISSING CHANNELS	02/19/81
M2 S2	VOL 3, #24	LOW FREQUENCY TONE DEVIATION	02/19/81
M2 S2	VOL 3, #25	HORN BLOWING OPTION OPERATING ERRATIC	02/19/81

05 S2	VOL 3, #26	EX-II STATION STAYS KEYED IN TRANSMIT	02/19/81
GN	VOL 3, #27	WARRANTY MATERIAL REIMBURSEMENT	02/20/81
52 71	VOL 3, #28	INTRINSICALLY SAFE PERSONAL PORTABLES	04/01/81
65 69	VOL 3, #29	FAILURE OF DIODES/FET ON M-II DFE	04/01/81
M2 S2	VOL 3, #30	COLLECTION TONE INTERMITTENTLY TO SHORT	04/01/81
05 06 08 15	VOL 3, #31	POTENTIALLY HAZARDOUS CAPACITORS	04/01/81
61 67 M2 S2		IN TX POWER AMPLIFIERS - ALL PRODUCTS	
61 67	VOL 3, #32	FALSING OF MASTR II CHANNEL GUARD	06/01/81
16 52 71	VOL 3, #33	PE & PY PUSH TO TALK	06/02/81
GN SV	VOL 3, #34	VEHICULAR RFI PROBLEMS	06/01/81
M4 M5 M6 M7	VOL 3, #35	SUPPORT PROGRAMS-RECENTLY ANNOUN. PROD.	06/01/81
P4			
67	VOL 3, #36	MASTR-II HIGH POWER VHF TUBED PA'S	06/17/81
13 61 65 67	VOL 3, #37	MECHANICAL STRAIN ON M-II PA	06/17/81
38	VOL 3, #38	4EX3A11 CAP REVISION	07/03/81
03	VOL 3, #39	PE/PY DESK CHARGERS	07/10/81
16 52 71	VOL 3, #40	PE/PY REGULATOR MODULE SLOW RISE TIME	07/10/81
32 67 72	VOL 3, #41	PREMATURE FAILURE OF HIGH VOLT. DIODES	07/20/81
33	VOL 3, #42	19A143533 PE GE-STAR MODULE	07/20/81
17 67	VOL 3, #43	ART WORK ERROR ON CONTROL SHELF	07/22/81
67	VOL 3, #44	FAILURES IN 75 W & 100 W UHF RF PAs	08/12/81
33	VOL 3, #45	FALSE KEY UP GE-STAR MOBILE ENCODERS	08/18/81
79 P2 P4	VOL 3, #46	MPR/MPX VEHICULAR CHARGER	08/31/81
M5	VOL 3, #47	C-II PROGRAMABLE CHANNEL GUARD	09/01/81
32 67	VOL 3, #48	HI POWER UHF PA 4EF6A	09/08/81
67	VOL 3, #49	75 W UHF POWER AMP BURNOUT	10/23/81
M5	VOL 3, #50	C-II,UHF-X (470-512 MHZ) MULTI FREQ BD	10/23/81
M5	VOL 3, #51	C-II CHANNEL GUARD HYBRID REPLACEMENTS	10/23/81
M1 M6 M7	VOL 3, #52	C/C/C GE-MARC V INSTALLATION	10/23/81
G5	VOL 3, #53	GE MARC 500 SUPPORT PROGRAM	11/20/81
64	VOL 3, #54	MASTR CONTROLLER AUDIO QUALITY	11/20/81
64	VOL 3, #54A	MASTR CONTROLLER AUDIO QUALITY	12/11/81
05 17 67	VOL 3, #55	RFI TO DC CONTROL FUNCTIONS IN BASE STA	11/20/81
08 15	VOL 3, #56	PINS PUSHING OUT OF CUSTOM MVP SYSTEM	11/20/81
61 65 67	VOL 3, #57	UHF MIXER & IF BOARD COMPATABILITY	11/20/81
61 65 67	VOL 3, #57A	UHF MIXER & IF BOARD COMPATABILITY	12/23/81
16 52 71	VOL 3, #58	PE HIGH BAND TRANSMITTER OSCILLATION	11/20/81
16 52 71	VOL 3, #58A	PE HIGH BAND TRANSMITTER OSCILLATION	12/14/81
67 72	VOL 3, #59	200 W UHF TUBE PA CONTINUED	11/20/81
M3	VOL 3, #60	PHOENIX (XTAL) RX SPURIOUS RESPONSE	11/20/81
M3 M5	VOL 3, #61	TWEET FREQUENCIES - PHOENIX & C-II	12/04/81
18 C1	VOL 3, #62	MAINTENANCE WARRANTY REPORT	12/04/81
67	VOL 3, #63	LBI'S FOR HIGH POWER SOLID STATE STA.	12/04/81
P2 P4	VOL 3, #64	MPR/MPX KNOBS CAPS DELETED	12/04/81
03 52 71 P6	VOL 3, #65	PE CHARGER CONTACTS	12/04/81
64	VOL 3, #66	MASTR CONTROLLER SEE TSM VOL 4 #14	12/11/81
P2	VOL 3, #67	MPR BCD FREQUENCY SELECT SWITCH	12/23/81
P2	VOL 3, #68	MPR ANTENNA STUDS	12/23/81
P2 P4	VOL 3, #69	MPR/MPX KNOBS - FALL OFF	12/23/81
M3	VOL 3, #70	PHOENIX UHF CONTROL STATIONS	12/23/81
GN SV	VOL 3, #71	RFI TO ELECTRONIC IGNITION	12/23/81
M5	VOL 2, #1	C-II OSC PART CHANGE-COLD TEMP PROBLEM	01/11/80
52 71	VOL 2, #2	PE WITH CCT AND GE-STAR - STAYS KEYED	01/17/80
GN	VOL 2, #3	RTV - NON-CORROSIVE RTV-162 & RTV-3145	02/07/80
GN	VOL 2, #4	PRINTED CIRCUIT BOARD REPAIR	02/19/80
61 65 67	VOL 2, #5	MASTR-II CG DECODE TIME LONG 19D417261	02/19/80
0371 P2 P4 79	VOL 2, #6	BATTERIES - RECHARGEABLE LIFE - ST-3301	02/19/80
80 M5	VOL 2, #7	C-II CRYSTAL OSC FREQ ADJUSTMENT	02/29/80
GN SV	VOL 2, #8	CMOS HANDLING INFORMATION	05/12/80
61 65 67	VOL 2, #9	M-II ICOM INTERCHANGABILITY-TSM V2 #9	05/21/80

67		VOL 2, #10	MASTR-II OUTPUT FILTER WITH Z-MATCHER	05/28/80
GN SV 61 65 67		VOL 2, #11	M-II SERVICE NEWS LETTER INDEX-GUTHRIE	06/09/80
M2 S2		VOL 2, #12	EX-II GE-MARC REVISIONS	07/11/80
80 M5		VOL 2, #13	C-II TX DISTORTION AT 300 Hz.	07/28/80
80 M5		VOL 2, #14	C-II FREQ SHIFT CAUSED BY THERMISTOR	07/28/80
79 P2		VOL 2, #15	MPR VEHICLE CHARGER ADJUSTMENT	07/30/80
61 65 67		VOL 2, #16	M-II ICOM DEAD 19A137763	08/29/80
80 M5		VOL 2, #17	C-II RX ATTACK TIME LONG	09/02/80
16		VOL 2, #18	PY UNSQUELCHES WITH FULL CHARGE BAT.	09/05/80
GN M2 SV 17 67		VOL 2, #19	VERSATONE NETWORKS SEE TSM VOL 5, #39	09/09/80
07 61 65		VOL 2, #20	C800/900 RFI VARIES RF POWER OUTPUT	10/20/80
18 GN M2 S2		VOL 2, #21	SYNTHESIZER DRIFT-DIVIDE-BY-N 74LS161	10/20/80
43 VEND		VOL 2, #22	IMTS GLENAYRE TERMINAL SUPPORT	10/20/80
38 52 71		VOL 2, #23	PORTABLE TEST CABLE 19C317633G1	10/20/80
16 52 71		VOL 2, #24	PE & PY SPEAKER MIC & CCT	10/20/80
67 S3		VOL 2, #25	M-II ANT MATCH TUNING	10/20/80
67 S3		VOL 2, #25A	M-II ANT MATCH TUNING	06/01/81
M2 S2		VOL 2, #26	EX-II GE-MARC SYNTHESIZER LOCK TIME	10/20/80
16 52 71		VOL 2, #27	PE & PY STAYS KEYED - SPEAKER-MIC-ANT	10/20/80
16 52 71		VOL 2, #28	PE & PY LOW TX DEVIATION-SPEAKER MIC	10/20/80
M2 S2		VOL 2, #29	EX-II GE-MARC TONE BD FALSING	10/20/80
72		VOL 2, #30	PRO-72 SHARED RPTR DROP OUT AUDIO MUTE	10/20/80
M2 S2		VOL 2, #31	EX-II GE-MARC LOW RF POWER OUTPUT	10/20/80
M2 S2 17		VOL 2, #32	EX-II GE-MARC ICOM FREQ DRIFT	10/20/80
80 M5		VOL 2, #33	C-II RECEIVER TWEET FREQ LIST	10/31/80
80 M5		VOL 2, #34	C-II POWER CABLE INTERCHANGABILITY	12/10/80
08 15		VOL 1, #1	CMVP - NOISE WHILE RX MUTED	09/11/78
16		VOL 1, #2	PY - TRANSMIT AUDIO DISTORTION	10/16/78
08 61 67		VOL 1, #3	STATEK CG XTALS NLA SEE TSM VOL 1, #26	10/31/78
52 71		VOL 1, #4	PE/PY BATTERY FAILURES	11/10/78
52 71		VOL 1, #5	PE/PY MODULE TEST PROCEDURE	11/13/78
03 04 52 71		VOL 1, #6	PE VEH CHARGER & PORTA-MOB-II 15W AUDIO	11/30/78
13 06 61 65 67		VOL 1, #7	MASTR-II PA's BROADBAND vs HI-Q LOADS	02/16/79
61 65 67		VOL 1, #8	MASTR-II HYBRID THICK-FILM MODULES	02/27/79
61 65 67		VOL 1, #9	MASTR-II LB 50W PA TRANSISTOR 19A116839	03/02/79
GN SV		VOL 1, #10	TRANSMITTER DEVIATION MEASUREMENTS	03/12/79
31 32 34		VOL 1, #11	PRO & EX - OVERSIZED 7984 TUBES	03/20/79
16		VOL 1, #12	PY REMOTE CG OPENS WITH NO TONE	03/20/79
61 65 67		VOL 1, #13	MASTR-II HB PLL EXCITER INT. LOCK	03/21/79
61 65 67 70		VOL 1, #14	MASTR-II FAST/SLOW SQUELCH DISABLE	03/21/79
M2 S2 M6 N7 TM		VOL 1, #15	800 MHz ANT TYPE-N CONNECTOR	03/29/79
67		VOL 1, #16	MASTR-II STANDBY BATTERY OPTIONS	03/29/79
61 65 67		VOL 1, #17	MASTR-II MODULE SUBSTITUTION	03/29/79
GN 61 67		VOL 1, #18	TSM ERRATA SHEET	04/06/79
06 18		VOL 1, #19	EX-II RCC/IMTS WON'T TX WHEN COLD	04/12/79
06 17 67		VOL 1, #20	800 MHz POWER CONTROL HYBRID 19A124149	04/12/79
03 04		VOL 1, #21	PM-II 3 RATE CHARGER LED MODIFICATION	04/26/79
03 52 71		VOL 1, #22	PE VEH CHARGER DEAD BATTERY OPTION	05/10/79
52 71		VOL 1, #23	PE CHANNEL GUARD ENCODE DIST. FROM RF	05/14/79
P2		VOL 1, #24	MPR SERVICE RECOMMENDATIONS	05/14/79
07 61 65		VOL 1, #25	C800/900 DIGITAL READOUT	05/21/79
GN		SPECIAL	TSM INDEX VOL 1, #1-25	05/21/79
08 61 67		VOL 1, #26	STATEK CG XTALS AVAILABLE AGAIN	05/22/79
07 61 65		VOL 1, #27	C800/900 MULTI-TONE CG ENCODE RFI	05/25/79
16 38 52 71		VOL 1, #28	PE TEST REG. 4EX18A10 & 4EX19A10	05/25/79
80 M5		VOL 1, #29	C-II DESK MIC, CG MONITOR WIRE LOOSE	06/01/79
16		VOL 1, #30	PY WON'T RETURN TO RX -PTT MODIFICATION	06/04/79
52 71 P2 P4 P5		VOL 1, #31	INTRINSICALLY SAFE SERVICING AND RATING	06/14/79
17 05 06 M2 S2		VOL 1, #32	EX-II 800 MHz PA OSCILATION AND BURN-UP	07/17/79
16 52 71		VOL 1, #33	RECHARGEABLE BATTERY FAILURES	07/17/79

80 M5	VOL 1, #34	C-II PART # MIC, VOL WRENCH, PROBE KIT	07/27/79
GN	VOL 1, #35	PROBLEM REPORTING PROCEDURES	08/06/79
GN SV	VOL 1, #36	BERYLLIUM OXIDE IN TRANSISTORS-HANDLING	08/13/79
16 52 71 VEND	VOL 1, #37	BATTERIES BY ALEXANDER - PROBLEMS	08/20/79
61 65 67	VOL 1, #38	MASTR-II HB PA PWR CONT. 19D429709G1	09/20/79
07	VOL 1, #39	C800/900 SWITCH LATCH LUBRICANT MS-122	09/20/79
16 52 71	VOL 1, #40	PE/PY REMOTE PTT RELAY FAILURES	10/23/79
50	VOL 1, #41	PR TX F1 SICOM INTERFERENCE FIT	10/24/79
67	VOL 1, #42	MASTR-II PA POWER CONT PASS XISTOR FAIL	11/07/79
29	VOL 1, #43	POWER CALL/SIREN CONTACTS	11/08/79
80 M5	VOL 1, #44	C-II VOLUME KNOB PICK UP A.M. BROADCAST	11/16/79
80 M5	VOL 1, #45	C-II UHF RX XTALS-HIGH SIDE INJECTION	11/16/79
80 M5	VOL 1, #46	C-II TX OSC FAILS/SLOW TO START COLD	12/07/79
M2 S2	VOL 1, #47	EX-II GE-MARC CLIP LEAD METHOD OF TEST	12/20/79



Product Codes

03	Chargers - PE, Porta-Mobile II, Pager
04	Porta-Mobile II
05	Mastr Executive II stations
06	MASTR Executive II mobile
08	Custom MVP mobile
09	C-400 Control unit
10	Executive Pager
11	C-500 Control unit
12	C-700 Control unit
13	MASTR Executive High Power mobile
15	5 Watt Custom MVP mobile
16	MVP Personal
17	MASTR II 800 MHz station
18	MASTR Executive II RCC & IMTS mobiles
21	Monitor Receiver
22	MASTR II IMTS stations
27	Porta-Mobile
28	External Tone decoders
29	Power Call/Siren
31	MASTR Professional series mobile
32	MASTR Professional Station
33	External Tone Encoder
34	Executive Mobile and Station
35	Transistorized Control Console
36	Monitor Receiver
38	Test Sets
39	Line Amplifier
41	Command Control Center
42	Pocket Mate
43	IMTS Terminal
44	Deskon and Pagecon
45	Royal Executive mobile
46	Royal Executive station
47	MASTR Royal Professional series mobile
49	MASTR Executive RCC mobile
50	Personal PR series
51	Personal Pager PCO
52	Personal PE series
54	MASTR Professional Satelite receiver
55	Voting Selector Panel
56	Royal Executive CIP mobile
57	MASTR Imperial series mobile

58 MASTR Progress Line Custom Executive mobile
59 Series 900 Paging terminal (IPAC)
60 Desk Top encoder (Type 99 Tone)
61 MASTR II "M" series mobile
62 Deskon II
63 Royal Executive station CIP
64 MASTR Controller
65 MASTR II "E" series mobile
66 MASTR Local Controller
67 MASTR II Stations
68 Personal Pager (PVO)
69 MASTR II Dual Front End
70 MASTR II Auxiliary receiver
71 Personal PE series portable
72 MASTR Professional 72 stations
75 Multiple Receiver Station
76 MASTR-II Weatherproof Control unit
79 MPR, MPX, MPS Chargers, MPI Multi-charger
80 Centry II mobile
82 MASTR Executive Vehicle repeater
83 Vehicle Repeater Mobile Detector/Personal receiver
91 Programmers & Programming Instructions - Service Parts Kits
A1 OpenSky Products
A3 P801
A7 M803
AR MASTR-II Aux Receiver
B2 Beacon II Monitor pager
B3 MASTR-II, IIe station
BS Orion low band station
C1 General Electric Mobile Telephone
C2 GE-MARC V Control unit
C3 Console & Switch - pushbutton
C4 C600/S600 Control unit
CC CIU/DVIU
CD CSD
CH Universal Charger
CM CMX-8630 800 MHz mobile
CN MCS mobile
CR C3 Maestro Concole
CS OpenSky Cell Site
D2 Orion
D5 GE-STAR decoder
DR Data/Dispatch radio & products
DS Orion Desktop / Wallmount Station
DT GE-NET TMX mobile
DX MDR mobile radio
FM FMD 8000
G5 GE-MARC 500 Programmable Paging Terminal
GN general
GM Panther 20x/40x/60xM Mobile
GP Panther 40x/60x/6xxP Portables
H1 Executive II Pager Multi Charger
H2 Chargers - M-PD/TPX/PLS/M-PA/MTL
H9 LPE-50, LPE-200
HA Jaguar 700P
HB Jaguar 725M
HG M7100 IP mobile
MAHM P5100
HT P7100 IP portable
KA Panther 300M mobile
KB Panther 300P portable

KD EDACS 300P
KE EDACS 500M
KH Panther 500P
KM KMC mobile
KP KPC portable KRD 103 111
M1 GE-MARC V Classic, RM & Duplex
M2 GE-MARC V mobile (Ex-II)
M3 Phoenix mobile
M4 MASTR Delta mobile
M5 Centry II mobile
M6 GE-MARC V Corona/Centura, Centura TC
M7 GE-MARC V Classic
MD EDACS MTD series mobile 800 MHz
ME IP Multisite switch
MG Monogram portable
MG1 Monogram mobile
MH Monogram Low Band portable
ML MLS, MLS-II mobile
MM Maintenance Manuals
MP MPI-II Personal portable
MS Multi-site Switch (EDACS CEC and Integrated Multi-site IMC)
MT MTD 900 MHz
NA Network Admin. Server
NG Interoperability Gateway
NM Regional/Central Network Manager
NS Network Switching Server
NW Network Products - CTI, Data Gateway
N3 Delta-S/SX Synthesized mobile
N5 Phoenix-S, SX, PSX, PSX-SE
N7 GE-MARC VE Classic II 800 MHz
N8 Rangr Desktop / Wallmount / PST Station
N9 Rangr Synthesized
NP MVS mobile
P1 GE-4000 Personal radio
P2 MPR Personal
P3 Power MASTR RF amplifier
P4 MPX Personal
P5 MPI Personal (not synthesized)
P6 MPE Personal series
P7 GE-MARC V Personal
P8 Executive II snf BEACON Monitor pagers
P9 MPS Personal (synthesized)
PA M-PA, MT-L Personal
PC PCS portable
PD M-PD Personal
PG GE-NET Portable
PK MRK Portable
PL PLS Personal (synthesized)
PM MDX and MDR
PS EDACS Site Controller
PV M-PD Voice Guard Personal
R2 DATA LINK DL100
RC RCN-1000, DDC-100, 24/46/66 Remote Controller
RV Desktop UHF Repeater DRC-200 KRD 103 121
S1 MASTR-II Trunking Repeater Station, GE-MARC
S2 GE-MARC V Control Stations (Ex-II) 800 MHz
S3 MASTR-II Station
S4 GE-NET 900 Station
S5 S-500 Control unit
S6 S-550 Control unit
S7 S-700 Control unit

S8 S-825 Control unit
S9 S-900 Control unit
SA SIM (Site Interface Module)
SC Simulcast
SD Prism MASTR-Station
SK OpenSky Skymaster Base Station
SM System Manager
SR MASTR-III Multiple/Aux Receiver
SS Software Services
ST MASTR-II & IIe EDACS Station
SV service
SX MASTR-III Station, Guard Dog, ELI Local Interconnect
T1 GE-STAR Cellular mobile
T2 GE-MINI Cellular portable telephone
T3 CARFONE Cellular mobile telephone
T4 CARFONE XR cellular
T6 Cellular Station radio equipment
T9 Cellular Station radio Equipment
TA CRCU Cellular Station
TC GE-MINI II Cellular Personal telephone
TD Mobile Dual Mode telephone
TF Mobile Dual mode telephone
TH CARFONE IV Series
TJ Cellular portable - OLIVIA
TL MDS mobile
TM TMX-8400 & 8600, 8210, 8310, 8510, 8712, 8825 trunked mobile
TP TPX Personal
TQ Programming Products
TS Cellular Dual Mode telephone
UP NPC-50 KRD 103 127 & NPC-200 KRD 103 117 Portable
V1 MASTR Executive II Vehicular repeater
VEND Vendor
VJ Digital/Analog Voter
VP EDACS Voter
VR Conventional Analog Voter 91
VV Voice Guard Digital Voter
QC01 Command Control Console Series 2500, 503, 502
QC04 GE-MARC V & V.E Telephone interconnect system
QC05 Voice Guard applications
QC06 External Tone Encoder/Decoders
QC07 EDACS Portables Prism HP/LPE-200, LPE-200 900, IPE-100/200
QC08 EDACS mobile LME-800, LME-900, Monogram 800

